

CHAVIRA QUALITY CONCRETE - Omar Chavira Olguin

A COA public right-of-way excavation inspection was performed **3017 11TH ST NW From 11th To Phoenix--2026000424EXC** on 1/29/2026 at 10:00 A.M. Below are your inspection results:

Inspected Infrastructure

- Curb and Gutter is formed - soil compacted
- **PASSED**
- Please respond to this email with the associated haul tickets within 24 hours of paving the referenced site.

This inspection was based on the submitted application, approved construction drawings, approved curb cut site plan, the City of Albuquerque Standard Specifications, and current site conditions. Please contact me if you require additional information.

IMPORTANT NOTE: The contractor is responsible for scheduling a SEPERATE pre-pour and post-pour inspection with the responsible Engineer of Record, Architect, or Designer.

Link to the COA Standard Drawings and Specifications: <https://www.cabq.gov/planning/development-review-services/design-review-construction-forms>

This inspection was based on the submitted application, traffic control plan (if applicable), the Manual on Uniform Traffic Control Devices (MUTCD), the City of Albuquerque Standard Specifications, and current site conditions. Please contact me if additional details are needed.



David A. Lujan

Inspector II

O 505.924.3673

C 505.250.2628

F 505.924.3408

cabq.gov/DMD