



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	A10E002A		Project Name:	Seville Subdivision	
NPDES Id. No.	Not identified		Location:	Brookline Dr. NW	
5/28/2021	Owner		Contractor		
Operator	John R. DeBassige				
Contact name & title	John R. DeBassige				
e-mail	jrdebassige@yahoo.com				
Contact Phone #	505-710-3775				
COA Inspector	Thomas Evans		Start/End Time:	2:45 PM-2:55 PM	
Construction Phase:	earthwork/grading				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	clear		Temperature:	~ 88	
Estimated date of last storm 0.25" or greater	5/3/2021				
Item Number	Deficiency/ Corrective Action				
1	Sediment in the street. Sweep and remove sediment from the street daily.				
2	Domestic waste on site. Remove domestic and construction waste daily and place into an approved waste container.				
3	No posting of NOI permit coverage. Post signage of NOI permit coverage in a location clearly visible to the public.				
4	No erosion and sediment controls along West boundary of the site. Install silt fence or another BMP along the West boundary.				
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	None on file	

Notes:	No activity during this inspection.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans 06/29/2021