NPDES Tracking No: NMR12 13648

ECS File: A11 Eou C



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information				
Project Name	Un su and Manchen				
and Location	(La Sea and Manchela				
Site Contact Name & Agency	Tun Newall AIC Gurd Contractor	Contact Phone #/ E-mail \(\mathcal{V}_{0/-\mathcal{V}_{6}} \)			
Date of Inspection	1-31-17	Start/End 1225 12155			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction	5 Jehilizes				
Type of Inspection:	4				
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 3	11 / Complaint Response • Follow-Up			
	Weather Information				
Weather at time of this inspect	ion? Rain · Sleet · Fog · Snowing · ·	Temperature: ~~ F° Windy			
	ince the site was Permitted? · Yes · No				
Amount: • < 1/4" • 1/4" to 3					
	Erosion & Sediment Control Inspec	tion			
Entrance / Track-Out	~~				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.					
Erosion Controls / Mulch, Seed, ~ 1/2 acre west of side that we god					
Housekeeping/Pollutant Controls Simelly					
Debris/Pollutants/Sediment in MS4					
• Notes					
Is site being maintained in compliance with the Drainage Ordinance? Yes No Cut + Ch 1-31-7 Signature Date					

ECS File: All Eolla




City of Albuquerque Stormwater Construction Site Inspection Report

	General Information			
Project Name and Location	Mo Maken Market place Unser one ne Mohin Ton Newell Contact Phone #/			
Site Contact Name & Agency	Ton Newell AIC Grand Comboshy Contact Phone #/ E-mail Yol - 4639			
Date of Inspection	12-22-16 Start/End Time 11:45/11:36			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction 600 Whom proving Corks				
Type of Inspection: Regular Dyring stor	m event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up			
	Weather Information			
Weather at time of this inspect • Clear • Cloudy	,			
Has there been a storm event s Amount: < 1/4" to				
	Erosion & Sediment Control Inspection			
 Entrance / Track-Out Sediment Controls / Silt F Check Dams, Waddles 	·			
Erosion Controls / Mulch, Seed, Cervit pollutars (5) Housekeeping/Pollutant Controls				
* Housekeeping/Pollutant Controls				
Debris/Pollutants/Sediment in MS4				
• Notes				
Is site being maintained in compliance with the Drainage Ordinance? Yes No Signature Date				

P. Marie



City of Albuquerque Stormwater Construction Site **Inspection Report**



TEN S				
	General Information			
Project Name and Location	McMahan Market place 5708 McMahan Blud NE			
Site Contact Name & Agency	Tom Newey			
	ASC General Contractor Contact Phone # 401-4639			
Date of Inspection	9-21-1816 Start/End 7:55/10:20			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater-Stormwater One			
Describe Present Phase of Construction Ordal Son excavel when				
Type of Inspection: Regular During storm event Post-storm event (> 0.5 inch) 311 / Complaint Response Follow-Up				
	Weather Information			
Weather at time of this inspection? Clear · Cloudy · Rain · Sleet · Fog · Snowing · Windy Has there been a storm event since the site was Permitted? · Yes · No Amount: · < 1/4" · 1/4" to 3/4" · > 3/4" · Snow"				
	Erosion & Sediment Control Inspection			
Entrance / Track-Out & - mifigaled				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc. **Description: Check Dams Ok mingular Ok mingular				
• Erosion Controls / Mulch, Seed,				
Housekeeping/Pollutant Controls a L1ML drash				
• Debris/Pollutants/Sediment in MS4				
• Notes No a	proved grading plan			
Is site being maintained in complian	ince with the Drainage Ordinance? Yes No Cut c clu 9-21-16 Signature Date			

ECS File: AI/EONC



City of Albuquerque Stormwater Construction Site Inspection Report

	C 17.642				
	General Information				
Project Name	McMaha Market place	da.			
	5708 McMahu Bud	NE			
Site Contact Name & Agency	Ton Newell autoch	Contact Phone #	505 861 - 4242		
Date of Inspection	9-13-16	Start/End Time	36/11:05		
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov				
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One				
Describe Present Phase of Construction Pough grading Stock piles or adjaced Lot					
Type of Inspection:		V			
Regular • During storm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up					
	Weather Information	71 -1010			
Weather at time of this inspect			perature: ~ 75 F°		
Clear · Cloudy · Rain · Sleet · Fog · Snowing · Windy					
Has there been a storm event since the site was Permitted? · Yes No Amount: · < 1/4" · 1/4" to 3/4" · > 3/4" · Snow"					
	Erosion & Sediment Control Inspection				
Entrance / Track-Out	10 entrace - has 2 sites w		2		
Sediment Controls / Silt Fence, Check Dams, Waddles, etc. Cold Security But on site west of McO's Cold Security But on the North This					
* Erosion Controls / Mulch, Seed, 10 Sedemble Bort west 514 of 514 - Clar hern					
Housekeeping/Pollutant Controls Trash					
• Debris/Pollutants/Sediment in MS4 _ ~ 0					
* Notes					
Is site being maintained in compliance with the Drainage Ordinance? Yes No Cute Clue 9-13-14 Signature Date					

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Wednesday, September 14, 2016 9:53 AM

To:

'grant@inspectionsplusinc.com'

Subject:

Mcmahon Marketplace SWPPP Inspection

Attachments:

no_track-out_pad.jpg; stockpile_egress.jpg; trash.jpg; west_edge.jpg

Grant,

Good morning.

Tom Newell's business card didn't have an e-mail address and I didn't want to send this to the property owner at this time. Please forward to Tom.

Issues at McMahon Marketplace:

- 1. No track out pad at exit to site being graded. I spoke with Tom and we agreed that he would put in two trackout pads: one at the entrance to the site being graded and another at the stockpile lot.
- 2. In addition, folks are driving out to McMahon next to the stockpile lot and are tracking-out sediment. Not sure if we can block this off. He said he will look into it.
- 3. A bit too much trash. He needs to keep a clean site.
- 4. There is no sediment BMP on the west edge. I think it is OK, if the berm/pile over there directs water to the north. A little bit of sediment that may run off the dirt pile will be filtered by the veg.
- 5. I didn't take a picture but we discussed a berm/silt fence at the north edge running a distance west from the exiting silt fence on the northern edge. Currently, flows from the site will drain west of the current silt fence installation

I told him I'd be back in a week to check-up on him.

Thanks, Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

Cherne, Curtis

From: Grant Morrison <grant@inspectionsplusinc.com>
Sent: Wednesday, September 14, 2016 1:35 PM

To: Cherne, Curtis

Subject: RE: Mcmahon Marketplace SWPPP Inspection

Curtis

I just went by and we're getting on this. We installed some silt fence about a week ago but it was such chaos they couldn't decide where they would enter, etc.

Anyway it will look good next time you go out. We're having to amend the SWPPP since they put the construction trailer and entrance to the west.

Grant Morrison, CPESC

Inspections Plus, Inc 4382 Alexander Blvd NE Albuquerque, NM 87107 Cell 505-489-5077 Off 505-344-9410

From: Cherne, Curtis [mailto:CCherne@cabq.gov]
Sent: Wednesday, September 14, 2016 9:53 AM

To: 'grant@inspectionsplusinc.com' <grant@inspectionsplusinc.com>

Subject: Mcmahon Marketplace SWPPP Inspection

Grant,

Good morning.

Tom Newell's business card didn't have an e-mail address and I didn't want to send this to the property owner at this time. Please forward to Tom.

Issues at McMahon Marketplace:

- 1. No track out pad at exit to site being graded. I spoke with Tom and we agreed that he would put in two trackout pads: one at the entrance to the site being graded and another at the stockpile lot.
- 2. In addition, folks are driving out to McMahon next to the stockpile lot and are tracking-out sediment. Not sure if we can block this off. He said he will look into it.
- 3. A bit too much trash. He needs to keep a clean site.
- 4. There is no sediment BMP on the west edge. I think it is OK, if the berm/pile over there directs water to the north. A little bit of sediment that may run off the dirt pile will be filtered by the veg.
- 5. I didn't take a picture but we discussed a berm/silt fence at the north edge running a distance west from the exiting silt fence on the northern edge. Currently, flows from the site will drain west of the current silt fence installation

I told him I'd be back in a week to check-up on him.

Thanks, Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Wednesday, September 14, 2016 9:53 AM

To:

'grant@inspectionsplusinc.com'

Subject:

Mcmahon Marketplace SWPPP Inspection

Attachments:

no_track-out_pad.jpg; stockpile_egress.jpg; trash.jpg; west_edge.jpg

Grant,

Good morning.

Tom Newell's business card didn't have an e-mail address and I didn't want to send this to the property owner at this time. Please forward to Tom.

Issues at McMahon Marketplace:

- 1. No track out pad at exit to site being graded. I spoke with Tom and we agreed that he would put in two trackout pads: one at the entrance to the site being graded and another at the stockpile lot.
- 2. In addition, folks are driving out to McMahon next to the stockpile lot and are tracking-out sediment. Not sure if we can block this off. He said he will look into it.
- 3. A bit too much trash. He needs to keep a clean site.
- 4. There is no sediment BMP on the west edge. I think it is OK, if the berm/pile over there directs water to the north. A little bit of sediment that may run off the dirt pile will be filtered by the veg.
- 5. I didn't take a picture but we discussed a berm/silt fence at the north edge running a distance west from the exiting silt fence on the northern edge. Currently, flows from the site will drain west of the current silt fence installation

I told him I'd be back in a week to check-up on him.

Thanks, Curtis Cherne, PE, QCIS Stormwater Quality Engineer COA 505-924-3420

"Cement (concrete, stucco, mortar...) pollution is preventable.....Let's prevent it. Thank you."