

## City of Albuquerque Stormwater Construction Site Inspection Report

**General Information** 

ESC File No. A11E		017 Project Name: Uns		er/McMahon Mixed Use Subdivision			
NPDES Id. No.		Location:		10745 Unser Blvd			
3/10/2021		Owner			Contractor		
Operator		JMD-McMahon, LLHolly Partners LLC.					
Contact name & title		Tushar Patel					
e-mail		tushar@tnigroup.com 362-1702					
Contact Phone #					St. 1/5 177		
COA Inspector		Doug Hughes			Start/End Time: 10am		
Construction Phase:		infrastructure			nearly complet	:e	Te u
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
Weather at time of i		nspection?	Clea	ır	Temper	ature: ~	45
Estimated date of last storm 0.25" or greater							
Item	Deficiency/ Corrective Action						
Number	Beneficiety, corrective riction						
	construction not started yet.						
				1			
2.1	Discharge off site?	(Y/N)	no			- 1 1-	
4	Self Inspection Reports		requested	Latest rep	oort Date:	8/25/20	)20
Notes:							
Natural undisturbed vegitation sampled by 100' transect sampling pionts every 3' - 34 poins total							
Sage bush - 6 points Senna phyllodinea 1 point grass 1 point Liter 3 points							
Cedar 1 point dirt 22 points = 35% ground cover native undisturbed							
- pania and - pani							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov