

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. A11E					ser/McMahon Mixed Use Subdivision		
NPDES Id. No.		Location:		10745 Unser Blvd			
1/6	/2022	Owner			Contractor		
Operator		JMD-McMahon, LLHolly Partners LLC.					
Contact name & title		Tushar Patel					
e-mail		tushar@tnjgroup.com					
Contact Phone #		362-1702					
COA Inspector		Doug Hughes			Start/End Time: 10am		
Construction Phase:					nearly complete		
Type of Inspection:		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of i				ear	Tempera		43
Estimated date of last stor		form 0.25" or greater		1/1/2022			
Item Number	Deficiency/ Corrective Action						
	none						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspec	tion Reports	s n/a	Latest rea	oort Date:	12/29/2	021
			.,, .,			, -3) -	
Notes:	Earthwork complete infrastructure under way.						
	along east boundary disruped silt fence there but repaires began immediately. The sign had						
been knocked down and that was being put back up at time of inspection. No sediment in adjacenr							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

streets. SWPPP not checked.

jhughes@cabq.gov

1/10/22

James D. Hughes