

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
ESC File No.	A11E		roject Name:	Un	Unser/McMahon Mixed Use Subdivision				
NPDES Id. No.	NMR10	JO4PN LC	ocation:		10745 Unser Blvd				
12/2	29/2022	Owner			Contractor				
Operator	Operator		Holly Partners LLC.			Tierra west			
Contact name & title		Yogesh Patel			Yogesh Patel				
e-mail		yogi1020@gmail.com			yogi1020@gmail.com				
Contact Ph	Contact Phone #		275-8223			275-8223			
COA Inspector		Doug Hughes			Start/End Tim	e: 2:15	PM		
Constru	Construction Phase:				oment onsite (inactive)				
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up		
Weath	er at time of i	inspection?	Cle	ear	Tempe	erature: ~	40		
Estimated	date of last s	storm 0.25" or				12/4/2022			
Item									
		Deficiency/ Corrective Action							
Number									
1	Silt fence need	Silt fence needs repaired or replaced							
2	Posting expired permit number must be updated on the sign. It is E2RC's sign, but they aren't hired.								
3	Sediment in the street needs removed and silt fence added to prevent reoccurance along Unser								
	entrance both sides. Sediment also at McMahon exit and inlets								
4	Inlet protection needs maintenance								
5	SWPPP not available								
6	Stabilization not complete, sparce grass, mulch gone, needs maintenance/reaplication								
2.1	Discharge off site?	(Y/N)	no						
4	Self Inspec	tion Reports	n/a	Latest rep	oort Date:				

Notes:	Subdivision complete, but no Building construction started on any of the sites.						
	City of Albuquerque Stermuster Increator Signature and date:	1/3/23					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

jhughes@cabq.gov

Doug Hughes (505) 924-3420

James D. Hughes