

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	A11E			Unser/McMahonLots1 & 3-7				
NPDES Id. No.	NMR1004PN		ocation:		10745 Unser Blvd			
4/5/2023		Owner		Contractor				
Operator		Holly Partners LLC.			Insight			
Contact name & title		Yogesh Patel			James Romero Sup			
e-mail		yogi1020@gmail.com			James@insightnm.com			
Contact Phone #		275-8223			934-2511			
COA Inspector		Doug Hughes			Start/End Time: 10:30AM			
Constru	ction Phase:	Building on lot 4 & both new and old disturbance on other lots						
Type of Inspection:		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	inspection?	Clea	ır	Temper	rature: ~	45	
Estimated	date of last s	storm 0.25" or	r greater			3/16/2023		
Item								
	Deficiency/ Corrective Action							
Number								
1	The Silt fence is full and the sediment must be removed. I recommend adding another Silt fence abou							
	to 8' uphill from the existing silt fence leaving room to remove the sediment from the lower silt fence						r silt fence.	
	CGP 2.2.3.c.i							
	Sodiment mus	Sediment must be removed from the streets both onsite and from Unser and McMahon. Your						
							-	
	contractor appears to be washing the street into the inlets as indicated by wet streets w					•	no rain.	
	Sediment mus	st be picked up	and removed not	washed into	the storm dra	ins, CGP2.2.4.d		
3	Self inspection	n reports are mi	issing since 2/15/	23. Email sigr	ned copies of a	II missing reports	to me.	
		-				0 - p - s		
4	Concrete was	Concrete wash-water has been dumped on the ground in several places on lot 4. All contaminated soil						
4	and dried concrete washout must be picked up and disposed into the waste containers. All future v							
				o and dispose	ed into the was	ste containers. Aii	iuture wasn-	
	water must be directed into lined containers.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	n/a	Latest rep	ort Date:	2/15/20)23	

Notes:	Subdivision complete, 2 buildings on lot 4 under roof.				
Lots 2, 8, a	and 9 have been transferred to new owners. Lot 4 construction disturbed lots 3 and 5 and				
added sto	ckpile on lot 1, Holly Partners LLC plans to build offices, first foundation just started. Tierra				
West has the SWPPP and is doing inspections. There isn't any Deligation of Authority so Yogesh Patel is					
the Operator according to the NOI. BMP instalation and maintenance says it is TBD.					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

4/6/2023

James D. Hughes