

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	A11E017		oject Name:	Unser/McMahonLots1 & 3-7				
NPDES Id. No.	NMR1004PN L		ocation:		10745 Unser Blvd			
7/3/2023		Owner		Contractor				
Operator			Holly Partners LLC.			Insight		
Contact name & title		Yogesh Patel			James Romero Sup			
e-mail		yogi1020@gmail.com			James@insightnm.com			
Contact Phone #		275-8223			934-2511			
COA Inspector		Doug Hughes			start/End Time: 10:30AM			
Construction Phase: Building on lot 4 & both new and old disturbance on other lots								
Type of Ir	rspection:	Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	Clea	r	Tempe	rature: ~	45	
Estimated	date of last s	torm 0.25" or	greater			3/16/2023		
Item								
	Deficiency/ Corrective Action							
Number								
1	The Silt fence is full and the sediment must be removed. I recommend adding another Silt fence about						ence about 6'	
	to 8' uphill from the existing silt fence leaving room to remove the sediment from the lowe					r silt fence.		
	CGP 2.2.3.c.i							
_								
2	Sediment must be removed from the streets both onsite and from Unser and McMahon. Yo contractor appears to be washing the street into the inlets as indicated by wet streets with Sediment must be picked up and removed not washed into the storm drains, CGP2.2.4.d							
						y wet streets with	no rain.	
						ins, CGP2.2.4.d		
	C 1C: 1:			22 5 11 1	1			
3	Self inspection	reports are mi	ssing since 2/15/.	23. Email sigr	ned copies of a	III missing reports	to me.	
4	4. Concrete wash-water has been dumped on the ground in several places on lot 4 . All contaminate						taminated	
			•	•	•	waste containers		
			•		poscu into the	waste containers	. All Tuture	
	wasn-water m	ust be airected	into lined contai	ners.				
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	n/a	Latest rep	oort Date:	2/15/20	023	

Notes:	Subdivision complete, 1st building on lot 4 just started.			
Lots 2, 8, a	and 9 have been transferred to new owners. Lot 4 construction disturbed lots 3 and 5 and			
added sto	ckpile on lot 1, Holly Partners LLC plans to build offices, first foundation just started. Tierra			
West has	the SWPPP and is doing inspections. There isn't any Deligation of Authority so Yogesh Patel is			
the Opera	tor according to the NOI. BMP instalation and maintenance says it is TBD.			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov