

INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION:	1/5/2022
COMPANY NAME:	Holly Partners, LLC
PROJECT NAME:	Unser & McMahon 19 Acres
LOCATION:	SW Corner of Unser Blvd. & McMahon, Albuquerque, New Mexico, 87114
TRACKING NO:	NMR1003PR
COMPLIANCE EVALUATION:	Unsatisfactory
TYPE OF INSPECTION:	7Day
START TIME:	9:45 AM
END TIME:	10:30 AM
INSPECTOR'S NAME:	Ray Welton
INSPECTOR'S TITLE:	NPDES Inspector
INSPECTOR'S QUALIFICATIONS:	StormwaterONE
INSPECTOR'S CONTACT:	505-400-7500
PHASE OF CONSTRUCTION:	 Clear and Grub ✓ Excavation ☐ Building (vertical) Rough Grading ✓ Infrastructure ☐ Final Grading Final Stabilization
WF.	ATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	No
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	39	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	No
ARE ANY DISCHARGES OCCURRING NOW?	Yes	No
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	NPDES Permit Notification	Reset	None	Entrance	1	EA	<u>Yes</u>
2	Silt Fence	None	Repair	Unser Perimeter	10	LF	Yes
	Silt Fence	Clean	None	Unser Perimeter	1000	LF	<u>Yes</u>
3	Concrete Washout	Update	None	Onsite	1	EA	Yes
4	Debris or Waste	Clean	None	Concrete Washout Area	1	EA	Yes
5	Construction Entrance	Clean	None	Entrance	1	EA	Yes

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	• Yes O No O N/A	Yes • No	SWPPP posting was on the ground at time of inspection. Posting requires reset.
2	Are steep slope areas not actively being worked properly stabilized?	Yes No N/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	○Yes ● No ○ N/A	Yes No	Silt fence on the Unser Blvd perimeter requires maintenance. Sediment built up on both sides of silt fence requires removal to ensure effective stabilization.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	• Yes ONo ON/A	Yes No	
5	Are discharge points and receiving waters free of any sediment deposits?	● Yes ○ No ○ N/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	○Yes ● No ○ N/A	Yes No	Concrete debris surrounding wash out requires cleaning and debris removal.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	○Yes ● No ○ N/A	Yes No	Concrete wash out onsite requires signage that indicates location and type.
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	• Yes O No O N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	Yes No N/A	Yes No	
10	Are offsite flows entering the construction site?	○Yes ● No ○ N/A	Yes • No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	○Yes ● No ○ N/A	Yes No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	○ Yes ● No ○ N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	● Yes ○ No ○ N/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	Yes No N/A	Yes No	SWPPP posting was on the ground at time of inspection. Posting requires reset. Silt fence on the Unser Blvd perimeter requires maintenance. Sediment built up on both sides of silt fence requires removal to ensure effective stabilization. Concrete debris surrounding wash out requires cleaning and debris removal. Concrete wash out onsite requires signage that indicates location and type.
15	Are changes to the SWPPP necessary at this time?	Yes No N/A	Yes No	No changes to the SWPPP are necessary at this time.
16	Are dust control measures being properly implemented?	• Yes O No O N/A	Yes No	Water truck was onsite at time of inspection. Ground was moist and dust was not present at time of inspection.
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	Yes No N/A	Yes No	Met with CABQ Air Quality Inspector onsite.

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Ray Welton	DATE:	January 06, 2022
SIGNATURE AND AFFILIATION:	Rayned W. Walter J.		

CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	DATE:
SIGNATURE:		