General Permit SWPPP Inspection					
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas		
Permit #:		Inspection Frequency:			
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain	

Inspection Form Instructions

Review each guestion for this inspection carefully, then answer YES. NO, or N/A (not applicable). If any of the items below are out of

compliance, press the "Add Action Item" button above to add a corrective action.					
General Information					
<u>Inspector's Qualifications</u> Trained and work experience - see inspector qualification page in section 2 of the SW	/PPP.				
Type of Inspection:	Regular During storm event				
	Post-storm event				
Weather Information					
<u>Last Storm Event Information</u> For information on the last storm event, see the weather event information at the en	nd of this inspection.				
Weather at time of this inspection?	Clear Cloudy Rain				
	Sleet Snowing High Winds				
	Partly Cloudy				
Have any discharges occurred since the last inspection?	Yes No				
If yes, what did the water look like at the time of the discharge?					
Are there any discharges at the time of this inspection?					
If yes, what did the water look like at the time of the discharge?					
Is a rain gauge installed on site?	Yes No				
If yes, where is it located?	Local rain data from noaa source				
Has the Rain Event Page been filled out?					
Are there SDS sheets on site?	Yes No				

If yes, where are they located?

Attached to swppp in insight trailer



General Permit SWPPP Inspection					
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas		
Permit #:		Inspection Frequency:			
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain	

Permit #:		Inspection Frequency:		
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rai
	ction ceases on the site for more tl on resumes.			
Date Constr	uction Stopped			
Date Constr	uction Resumed			
Measures Ta	aken to Stabilize the Site:			
Constructi	on Phasing			
	tage of construction the project is in, and	record dates when activitie	s started and were compl	eted.
Installed BM	lPs .		ompleted	
Started:				
Starteu.		0.	2/28/2023	
Completed:				
Site Clearing	g and Grading	C	ompleted	
Started:				
Startea.		0	2/28/2023	
Completed:				
Installing Ut	ilities		lot Started	
Started:				
Completed:				
Building Stru	ucture			
J		_ ^	lot Started	
Started:				
Completed:				

Not Started

Started:

Paving and Walks



General Permit SWPPP Inspection					
Site Name:	<u>Unser and McMahon</u> <u>10724 Capricorn Pl NW, Albuquerque, NM 87114</u>	Inspector:	Ron Olivas		
Permit #:		Inspection Frequency:			
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain	

Site Name:	<u>10724 Capricorn Pl NW, Albuquerque, NM 87114</u>	inspector:	RON Olivas
Permit #:		Inspection Frequency:	
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation 48h Foreca Tuesday, March 21, 2023, 0.38" 22% Chance of
Completed:			
Final Gradin	g/Stabilize Site		Not Started
Started:			
Completed:			
Other			Not Started
Started:			
Site-specif			
The corrective	actions initiated and date completed are in t	he Corrective Action Log	
List of BMPs	Installed:		illt fencing Inlet covers and protective vattle
Are all of the	e above controls installed?	Υ	res No
Do any of th	e above controls need maintenance?	Y	/es No
,	controls have not been installed or rece, please list the control and explain.	· F r n 1	Routine maintenance of silt fencing equired at SW corner of lot 1. naintenance required on silt fencing ,lot , east side near T intersection.Vehicles driving over silt fencing onto lot 1.
Are the BMP	s shown on the map?	Υ	/es No
Were there a	any changes to the SWPPP?	[<u></u>	ves No

Were the changes to the SWPPP implemented within 7 days?

Yes

List any new BMPs needed:

Has the SWPPP been updated?



General Permit SWPPP Inspection					
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas		
Permit #:		Inspection Frequency:			
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain	

Notes:	
Oversight Issues	
A list of corrective actions will be supplied with this inspection.	
1. Are all slopes and disturbed areas not actively being worked properly stabil	ized?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected	with barriers or similar BMPs?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
3. Are perimeter controls and sediment barriers adequately installed (keyed in	nto substrate) and maintained?
Implemented?	Yes No N/A
Maintenance Required?	Yes No N/A
4. Are discharge points and receiving waters free of any sediment deposits?	
Implemented?	Yes No N/A
Maintenance Required?	

Yes

No

N/A

5. Are storm drain inlets properly protected?

Implemented?

Yes No N/A

Maintenance Required?

6. Is the construction exit preventing sediment from being tracked into the street?

Implemented?



General Permit SWPPP Inspection					
Site Name:	<u>Unser and McMahon</u> <u>10724 Capricorn Pl NW, Albuquerque, NM 87114</u>	Inspector:	Ron Olivas		
Permit #:		Inspection Frequency:			
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain	

Site Name:	<u>Onser and McManon</u> 10724 Capricorn Pl NW, Albuquergue, NM 87114	Inspector:	Ron Olivas
Permit #:		Inspection Frequency:	
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation 48h Forecas: Tuesday, March 21, 2023, 0.38" 22% Chance of R
Maintenance	e Required?	У	res No N/A
7. ls trash/litt	er from work areas collected and placed i	n dumpsters?	
Implemente	d?	Y	res No N/A
Maintenance	e Required?	У	res No N/A
8. Are washou	<u>ut facilities (e.g., paint, stucco, concrete) a</u>	<u>vailable, clearly marked, a</u>	nd maintained?
Implemente	d?	Y	res No N/A
Maintenance	e Required?	Y	res No N/A
9. Are vehicle material?	and equipment fueling, cleaning, and ma	<u>intenance areas free of spi</u>	<u>lls, leaks, or any other deleterious</u>
Implemente	d?	У	res No N/A
Maintenance	e Required	Y	res No N/A
10. Are mater	ials that are potential storm water conta	minants stored inside or ur	nder cover?
Implemente	d?	У	res No N/A
Maintenance	e Required?	Y	res No N/A
11. Are non-st	<u>corm water discharges (e.g., wash water, c</u>	dewatering) properly contro	blled?
Implemente	d?	Υ	res No N/A
Maintenance	e Required?	У	res No N/A
12. Has the Si	<u>te map been updated to reflect current co</u>	onditions?	
Implemente	d?	Y	res No N/A
Maintenance	e Required?		

Yes

No



General Permit SWPPP Inspection					
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas		
Permit #:		Inspection Frequency:			
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain	

13. Is the NOI posted?

Implemented?

	Yes	INO	N/A
Maintenance Required?	Yes	No	N/A
14. Were previous corrections made within 7 days of last inspection or before the	<u>ıe next</u>	storm	event?
Implemented?	Yes	No	N/A
Maintenance Required?			

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes No

No. a Nice Nice

Have there been any reportable quantities releases of hazardous materials?

Yes No

Additional Notes

East side of lots 5-7 recent improvement and upgraded maintenance to remove buildup on silt fencing *****vehicles driving over silt fencing onto lot 1****** Routine maintenance needed at SW corner of lot 1 Sediment beginning to overtake silt fencing at NE corner of lot 1

N/A



General Permit SWPPP Inspection							
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas				
Permit #:		Inspection Frequency:					
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain			

Certification & Signatures

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X Ron Olivas Date April 12, 2023 at 9:42:37 AM MDT

Title Inspector



General Permit SWPPP Inspection							
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas				
Permit #:		Inspection Frequency:					
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain			

Weather History



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



General Permit SWPPP Inspection							
Site Name:	<u>Unser and McMahon</u> 10724 Capricorn Pl NW, Albuquerque, NM 87114	Inspector:	Ron Olivas				
Permit #:		Inspection Frequency:					
Date of Visit:	Mar 22, 2023, 10:39:42 AM	Last Rain Event Tuesday, March 21, 2023, 0.38"	Last Precipitation Tuesday, March 21, 2023, 0.38"	48h Forecast 22% Chance of Rain			

There Are No Action Items