

**From:** Evans, Thomas C.  
**To:** ["startrustofnm@yahoo.com"](mailto:startrustofnm@yahoo.com); ["mntahat10@gmail.com"](mailto:mntahat10@gmail.com)  
**Cc:** [Hughes, James D.](#)  
**Subject:** Apartments on Buglo - 5530 Buglo Ave. NW; Permit # NMR1003YA; ESC # B11E013  
**Date:** Wednesday, June 16, 2021 1:39:00 PM  
**Attachments:** [image001.jpg](#)  
[B11E013 21.06.14.21F\\_Inspection.pdf](#)

---

Good afternoon Gentlemen,

An inspection was conducted at the Buglo site on Monday, June 14, 2021. We walked the site with Mr. Tahat and addressed all previous issues. The following items were discussed with any actions that need to be taken:

1. The hydromulch on the West half of the site (flat areas) has deteriorated and its condition should be monitored on the upcoming self-inspection reports.
2. The strip of land South of the site will act as a buffer. This needs to be noted on the site map and in the ESC Plan. Please provide copies when completed.
3. Upon moving the pile of dirt, a sediment trap was created at the SE corner. This needs to be noted on the site map and in the ESC Plan as well.
4. A formal submittal of the updated map is required for approval prior to obtaining a building permit.

Please feel free to contact me with any questions.

Thank you.

Tommy

[cid:image003.jpg@01D41F50.A8AE0A90](#)



**Thomas Evans**

Stormwater Inspector, SWQ

o 505.803-6215

e [tevans@cabq.gov](mailto:tevans@cabq.gov)

[cabq.gov/planning](http://cabq.gov/planning)