




Inspections Plus, Inc.

Engineer Stamp



### Legend

#### Erosion Sediment Control Plan

- Project Perimeter & Disturbed Area
- Silt Fence
- Pre Flow
- Flow
- Outfall
- Posting Sign
- Natural Buffer Zone / Maintain Existing Vegetation
- Staging Area
- Stabilized Construction Entrance
- Trash Receptacle
- Chemical Toilet
- Concrete Washout
- Retention Pond
- Rip Rap
- Proposed inlet with protection
- Retaining Wall  
(To be done at the end of the project for final stabilization)

### Eagle Ranch NM MVD

Receiving Waters: Calabacillas Arroyo is located 428 yards to the NorthEast.

Critical Habitat: Rio Grande is located 0.86 miles to the SouthEast.

Impairments: None

Grade: Before 0.5% to 2% Variable After 0.5% to 4 % variable