

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Ascension						
Location:		8814 Horizon						
Site Contact Name &		Brian McCarthy		ESC File No.		B17E006		
Agency		Brian@Abrazo	ohomes.com	NPDES Id. No.		NMR1002JR		
Inspection			art/End Time: 11:	30/11:59AM				
	water Inspecto	ר: טכ	oug Hughes	Cra	-11 ₋ _			
Construction Phase: Type of Inspection:		Regular	Storm Event	Grad Post Storm E	ung	311/Complaint	Follow Up	
Type of it	ispection.	Regulai	Storiii Everiti	POST STOTTILE	Verit >0.23	311/Complaint	Trollow op	
Weath	er at time of i	nspection?	Cloud	ay I	Tempe	rature: ~	35	
Estimated	date of last s	torm 0.25" or greater			12/24/2019			
Item		12/2 // 2013						
	Deficiency/ Corrective Action							
Number								
1	Track out at no	Track out at north entrance.						
2	East silt fence has big hole north end and sediment offsite. Also sediment offsite in SE corner.							
						_		
	 							
2.1	Discharge off site?	/v/ki\	Voc.	T				
2.1		(Y/N)	Yes	<u> </u>				
3	Self Inspect	tion Reports		Latest rep	ort Date:	n/a		
Notes:								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

James D. Hughes