

City of Albuquerque Stormwater Construction Site Inspection Report

General Information										
Project Name	2:	Ascension								
Location:		8814 Horizon								
Site Contact Name &		Brian McCarthy ESC File No. B17E006								
Agency		Brian@Abraz	<u>ohomes.com</u>	NPDES Id. No.		NMR1002JR				
Inspection Date:			art/End Time: 11	:30/11:59AM						
CoA Stormwa	ter Inspecto	r: Do	oug Hughes							
Construction Phase:				Gra	ding		_			
Type of Insp	pection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up			
Weather	at time of i	nspection?	Clou	ay	Tempe	erature: ~	35			
Estimated d	<u>ate of last s</u>	storm 0.25" or	greater			12/24/2019				
Item			_							
			Deficien	cy/ Correctiv	e Action					
Number										
1 Tr	rack out at n	orth entrance.								
2 Ea	East silt fence has big hole north end and sediment offsite. Also sediment offsite in SE corner.									
		_								
┝───┼										
2.1 Dis	scharge off site?	(Y/N)	Yes							
3	Self Inspect	tion Reports		Latest rep	ort Date:	n/a				

Notes:		

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov