

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nar	ne:	Ascension						
Location:		8814 Horizo	n					
Site Contact Name & Agency		Brian McCa		ESC File No.		B17E006		
		brian@Abrazohomes.com		NPDES Id. No.		NMR1002JR		
Inspection Date:		03/20/20 Start/End Time: 08				WWW.IOOZJK		
CoA Stormwater Inspecto								
Construction Phase: earthwork								
Type of Inspection:						1044/0 1::	l le 11	
Type of Ir	ispection:	Regular	Storm Event	Post Storm E	vent >0.25	311/Complaint	x Follow Up	
							37*	
Estimated date of last storm 0.25" or greater								
Item								
	Deficiency/ Corrective Action							
Number								
	all previous isswues mitigated, no nnew issues observed with this inspection							
	. , ,							
2.1	Discharge off site?	(Y/N)	No					
4	Salf Inchact	tion Poport	_	Latest ren	ort Dato:	3/2/2	020	
4	Self Inspect	ion keport	5	Latest rep	ort Date.	3/2/2	.020	
Notes:								
-								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

03/20/20