

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Ascension						
Location:		8814 Horizon						
Site Cont	act Name &	Brian McCarthy		ESC File No.		B17E006		
Agency		Brian@Abraz	ohomes.com	NPDES Id. No.		NMR1002JR		
Inspection			art/End Time: 11:	:50/11:59AM				
CoA Storm	water Inspecto	r: D	oug Hughes	C				
Construction Phase: Type of Inspection:		Regular	Storm Event	Grad Post Storm E	ding	311/Complaint	Trallandle	
Type of II	ispection.	Regular	Storm Event	POST STOTILE	vent >0.25	1311/Complaint	Follow Up	
Weath	er at time of i	nspection?	Cloud	ay T	Temper	rature: ~	35	
Estimated	date of last s	torm 0.25" or greater			11/27/2019			
	date of last s	11/2//2015						
Item	Deficiency/ Corrective Action							
Number								
1	Construction entrances incomplete and minor track out at north entrance.							
2	East silt fence not anchored properly, some holes under fence but no discharge.							
3	Provide self-inspection and corrective action reports.							
			_					
2.1	Discharge off site?	(Y/N)	No					
3	_	tion Reports		Latest rep	ort Date:	n/a		
					0.02000	, -		
Notes:								
						_		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov