ECS File: **B18E019** 



## City of Albuquerque Stormwater Construction Site Inspection Report

AND THE PROPERTY OF THE PARTY O	General Information
Project Name and Location	5656 lasalera Sance
Site Contact Name & Agency	Mechabier Construction Contact Phone #/ 505  E-mail 3M-7706
Date of Inspection	1-13-17 Start/End Time 1205/12:18
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One
Describe Present Phase of Construction	Stobilizia
Type of Inspection:	
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 311 / Complaint Response • Follow-Up
	Weather Information
Weather at time of this inspect	ion? Temperature: ~_50_ F°
	Rain · Sleet · Fog · Snowing · Windy
	ince the site was Permitted? · Yes · No
<b>Amount:</b> • < 1/4" • 1/4" to	
	Erosion & Sediment Control Inspection
■ Entrance / Track-Out	MA
<ul> <li>Sediment Controls / Silt I</li> <li>Check Dams, Waddles</li> </ul>	, etc
<ul> <li>Erosion Controls / Mulch</li> </ul>	, Seed, Drovel, asphat, Sodemulation pand
<ul> <li>Housekeeping/Pollutant (</li> </ul>	Controls
<ul> <li>Debris/Pollutants/Sedime</li> </ul>	nt in MS4
Notes	
Is site being maintained in complia	nce with the Drainage Ordinance? Yes No Cut a ch 1-13-17  Signature Date