

City of Albuquerque Stormwater Construction Site Inspection Report

| General Information | | | | | | | | |
|--|---|--------------------------------|--------------|---------------------------|--------------------|---------------------|------------|--|
| ESC File No. | B18E029 | | roject Name: | The Peaks by Markana Ph 2 | | | | |
| NPDES Id. No. | NMR1004QW | | ocation: | 6700 Modesto Avenue NE | | | | |
| 6/29/2022 | | Owner | | Contractor | | | | |
| Operator | | KLA 9, LLC. | | Kasam Construction | | | | |
| Contact name & title | | Faizel Kassam | | Stephen Pendergraft | | | | |
| e-mail | | fkassam@legacy-hospitality.com | | Spendergraft@Legacydm.net | | | | |
| Contact Phone # | | 505-489-4474 | | | 720-7188 | | | |
| COA Inspector | | Doug Hughes | | Start/End Time | e: 2:00 AM | | | |
| Construction Phase: | | | | aging | | | | |
| Type of Inspection: | | Regular | Storm Event | Past Storm | Event >0.25" | 311/Complaint | Follow Up | |
| Weather at time of inspection? Clear Temperature: ~ 94 | | | | | | | | |
| Estimated | date of last s | storm 0.25" oi | r greater | | 6/27/2022 | | | |
| Item | | | | | | | | |
| Number | Deficiency/ Corrective Action | | | | | | | |
| 1 | SWPPP was up-to-date and available, Posting was being put up by Stephen, BMP instalation was nearly | | | | | | was nearly | |
| | complete. So previous violations were mitigated. | | | | | | , | |
| 2 | The SWPPP map needs updated with current conditions showing mulch sock instead of sil | | | | | ock instead of silt | fence, and | |
| | area of disturbance south of site on City property. Also show the planned trail co | | | | trail connection a | nd easement | | |
| | to Phase 1 and add landscaping stabilization to offsite disturbed areas. | | | | | | | |
| | | | | | | | | |
| 3 | Please provide a copy of the latest self-inspection report. | | | | | | | |
| | רובמצב או טאועב מ נטאא טו נוופ ומנפגו גפוו-וווגאפנגוטוו ופאטונ. | | | | | | | |
| 4 | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| 2.1 | Discharge off site? | (Y/N) | no | | | | | |
| 4 | Self Inspec | tion Reports | Requested | Latest re | port Date: | n/a | | |

| Notes: | |
|----------|--|
| SWPPP wa | as in Stephen's truck but he plans to put it in a lockbox near the north gate. |
| | |
| | |
| | |
| | |

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505-924-3420) jhughes@cabq.gov