

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	B18E029		roject Name:	The Peaks by Markana Ph 2				
NPDES Id. No.	NMR1004QW		ocation:		6500 Glendale Avenue NE			
11/15/2023 Owner		Owner	ner		Contractor			
Operator		KLA 9, LLC.			Kasam Construction			
Contact name & title		Faizel Kassam			Stephen Pendergraft			
e-mail		fkassam@legacy-hospitality.com			Spendergraft@Legacydm.net			
Contact Phone #		505-489-4474			720-7188			
COA Inspector		Doug Hughes			Start/End Time	ne: 10:30am		
Construction Phase:		Sta			aging			
Type of Ir	spection:	Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	spection? Cloudy Temperature: ~			rature: ~	55		
Estimated	date of last s	torm 0.25" oı	r greater		8/8/2023			
Item								
	Deficiency/ Corrective Action							
Number								
1	<b>SWPPP</b> - The offsite areas were added to the SWPPP map, but specifications for perimeter controls and							
	stabilization were still missing on the offsite 40' to 50' wide strip of land disturbing activities located							
	north of Modesto Ave and east of Glendale Ave on the Pueblo of Sandia's property in violation of CGP							
	2.2.3 and CGP 2.2.14 respectively. Self-inspections were not performed during the 497 days from							
	6/29/22 to 11/8/23. At least 35 inspections were missed at a rate of one inspection every two weeks, not							
	counting any missed rain event inspections. <b>Required Mitigation</b> : Add controls to the SWPPP map.							
2	BMPs - Perime	eter controls an	ıd stabilization ar	e still missing	on the offsite	40' to 50' wide str	ip of land	
	disturbing activities located north of Modesto Ave and east of Glendale Ave on the Pueblo o						of Sandia's	
	property in vic	olation of CGP 2	2.2.3 and CGP 2.2	.14 respectiv	ely. Constructi	ion Exits(CE) had be	een reset	
	onsite, but they didn't extend through the ROW to the paved city street. <b>Required Miti</b>							
	missing BMPs.							
3	HIISSIIIE DIVIPS.							
<del></del>								
2.1	Discharge off site?	(Y/N)	no					
4		tion Reports	35 missed	Latest re	port Date:	11/8/20	023	

Notes:	
SWPPP wa	as in the construction trailer, and an updated map and inspection report were e-mailed the
next day. S	Self-inspections were not performed during the 497 days from 6/29/22 to 11/8/23. At least 35
inspection	s were missed at a rate of one inspection every two weeks, not counting the missed rain event
inspection	S.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov