

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:			Estates at Glendale Ph 3					
Location:			8000 Glendale NE		B19E027			
Site Cont	act Name &	Randy Schn	Randy Schmille		B19E027			
Agency				NPDES Id. No.		NMR1001AX		
Inspection Date:		05/10/19	Start/End Time:	10:05	10:25			
CoA Stormwater Inspector: Curtis Cherne								
	tion Phase:					cting homes		
Type of Ir	spection:	Regular	X Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
36141-					1 45 4			
Weatne	er at time of	f inspection?	nspection? rain torm 0.25" or greater			egrees		
Estimateu	date or last	Storm U.25	or greater	30 Tay 6 Tay 10 Tay	4/22/2019			
Item	Deficiency/ Corrective Action							
Number	Deficiency/ corrective Action							
1	Construction and domestic waste not in an acceptable container in various locations through-out site							
2	Domestic waste at subdivision outfall							
3	No sediment BMP on lot with dirt ramp							
4	Too much dirt in the street including the dirt ramp							
-,	Too made after the street moraling the after tamp							
		<u> </u>						
		- W-F						
					<u>.                                    </u>			
2.1	Discharge off site	? (Y/N)	No	$\top$				
4		ection Report		Latest re	port Date:	3/1/20	19	
Notes:								
Will need to replace inlet protection soon - recommend cocoa mat or mulch sock								
Subcontractor driving on lots to the east - blue truck								
	-					-		

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE 505-924-3420

ccherne@cabq.gov

05/10/19 Cuto c Chine