

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	B20E			8400 & 8420 Glendale Ave NE			
NPDES Id. No.		Location:			8400 & 8420 Glendale Ave NE		
	5/2020	Property Own			Contractor		
Operator		Las Ventanas NM, Inc					
Contact name & title		Scott Ashcraft					
e-mail		tscott@lasventanasnm.com 505-362-6824					
Contact Phone #		l l			0 /5 . 5.		
COA Inspector		Doug Hughes			Start/End Time: 10am		
Construction Phase:					hwork		
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
Weath	<u>er at time of i</u>	nspection?	Clea	ar	Tempera	ature: ~	69
Estimated date of last storm 0.25" or greater							
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	The stock piles were graded smooth ready for seed, silt fence in place and fill removed from floodplain						
2	The disturbed area is more than 1 acre so NPDES permit coverage is required and both the NOI						
_	ESC Plan still have not been submited to the City						
	250 Figure 110 to been submitted to the only						
2.1	Discharge off site?	(Y/N)					
4	Self Inspect	tion Reports	requested.	Latest ren	oort Date:	n/a	
7	Jen mapee	tion reports	requesteu.	Latestic	ort bate.	11/ 4	
Notos							
Notes:							
Violation Letter sent to owner with \$500 fine.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov