

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. B20E06				8500 Glendale			
NPDES Id. No.		Location:			8500 Glendale		
10/9/2020		Property Owner			Contractor		
Operator		John Jones			Mark Homes		
Contact name & title		John Jones					
e-mail		rtmf91@gmail.com					
Contact Ph	one #	505-480-4537					
COA Insp		Doug Hughes			Start/End Time: 8 - 9am		
Construction Phase:					rtical		
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up
Weathe	er at time of i	nspection?	Cle	ar	Temper	ature: ~	76
Weather at time of inspection? Clear Temperature: ~ 76 Estimated date of last storm 0.25" or greater							
Item							
Number	Deficiency/ Corrective Action						
1	Required NPDES permit coverage is missing						
2	BMPs missing						
3	Selfinspection reports required						
4							
2.4	Discharge # 11.2	(M/NI)	NI-	1			
2.1	Discharge off site?	(Y/N)	No	l otoot see	aart Data:	m /-	
4	sen inspect	tion Reports		Latest rep	oort Date:	n/a	
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

James D. <u>Hug</u>hes