

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	B20E067		Project Name:		8500 Glendale		
NPDES Id. No.	NMR10	U3FQ Location:		8500 Glendale			
	Property Owner				Contractor		
Operator		John Jones			Mark Homes		
Contact name & title		John Jones					
e-mail Contact Phone #		rtmf91@gmail.com 505-480-4537					
					Chart / Fred Times		
COA Inspector		Doug Hughes			Start/End Time: 10am		
Construction Phase:					rtical		
Type of Inspection:		Regular	Storm Event	•	Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ∼ 66							
Estimated date of last storm 0.25" or greater							
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
	Required NPDES permit coverage is missing						
2	BMPs missing						
3	Selfinspection reports required						
4	Concrete washout in acceptable contaners only, Mitigate spills.						
7	esticited washout in acceptable containers strip, mitigate spinsi						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	requested	Latest rei	oort Date:	n/a	
•						, -	
Notes:							
. 10103.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov