

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C09E001H		Project Name:		Volcano Mesa Subdivision			
NPDES Id. No.	NMR1004HB		Location:		6800 Oakridge St. NW			
10/16/2023		Owner		Contractor				
Operator		DH Horton			Salls Brothers			
Contact name & title		Todd Warmkessel			Mathew Dyer			
e-mail		TWarmkessel@drhorton.com			mdyer@sallsbrothers.com 252-9245			
Contact Phone #		225-4760			Ţ			
COA Inspector		Doug Hughes			Start/End Time: 10:30am			
	ction Phase:				n & Final Stabilization			
	spection:	Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
	<u>er at time of i</u>					erature: ~ 60		
Estimated date of last storm 0.25" or greater 9/13/2023								
Item	D.C							
Number	Deficiency/ Corrective Action							
1	The SWPPP wasn't up-to-date. Required mitigation: The SWPPP, including Self Inspection Reports and							
	Corrective Action Reports, must be kept up-to-date per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3							
	and 7.3 and City Ordinance § 14-5-2-11(C)(1). If an on-site location is unavailable to keep the SWPPP							
	when no personnel are present, notice of the plan's location must be posted near the main entrance							
	your construction site CGP 7.3.							
	BMPs - The cut-back curbs are too shallow (see detail). Inlet Protection mulch socks is unacceptable.							
	Instead place sand/rock bags upstream of each inlet. Do not block inlets!!! Perimiter controls are missing							
	between street ansd landscaped areas. Use staked mulch sock between street and landscaped areas							
	during construction and until stabilized. Prevent traffic on recently stabelized east slope.							
2	Stabilization is missing causing erosion at the storm outfall. Required mitigation: Stabilize the disturbed							
	portion of the HOA Pond per COA Std Sec 1013.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	o OK	Latest re	port Date:	10/10/	2023	
Notes:				•	•			
	D and roports	are in a loc	kbox on the bacl	of the Bost	ing cian			
THE SWEE	i and reports	5 a1 C 111 a 100	KDOX OII LIIE DALI	VOI LITE FUSE	iiig sigii.			

City of Albuquerque Stormwater Inspector Signature and date: 10/17/23

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov

James D. Hughes