

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
ESC File No.	. C09E001H			oject Name:		Volcano Mesa Subdivision			
NPDES Id. No.	1004HB	04HB Location:			6800 Oakridge St. NW				
7/8/2024 Owner				Contracto					
Operator		DR Horton							
Contact nai		Joseph Cordero							
e-mail		jacordero@drhorton.com							
Contact Ph	505-991-	505-991-5266							
COA Insp	Chancel	Chancellor English			Start/End Time: 10am				
	tion Phase:						n & Final Stabilization		
Type of Inspection:		Regular		Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time o	f inspection	nspection? Clear			Temperature: ~ 85			
Estimated date of last storm 0.25" or greater 6/30/2024									
Item	PO								
Number									
1	The SWPPP and self-inspection reports were unavailable at the time of inspection in violation of CGP								
	Parts 4.7.3 and 7.3. Required mitigation: You must keep a current copy of your SWPPP and a copy of								
	all inspection reports at the site or at an easily accessible location where they can be made								
	immediately available at the time of an on-site inspection per CGP Parts 4.7.3 and 7.3.								
2.1	Discharge off site? (Y/N)			no					
4	Self Inspection Reports			no	Latest re	oort Date: N/A			
Notes:									
The doc-b	ox was emp	ty at the tir	ne o	f inspection. A	mend the S	WPPP and pe	rmit coverage p	osting to	
ensure proper contact information is up-to-date. All perimeter areas have been stabilized.									

City of Albuquerque Stormwater Inspector Signature and date: 7/9/2024

Contact information: Chancellor English 505-924-3325

cenglish@cabq.gov

Chancellor English