



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C09E012A	Project Name:	Durango Units 3 and 4		
NPDES Id. No.	NMR1003L6	Location:	Woodmont Ave. and Sunlight Peak		
4/20/2021	Owner	Contractor			
Operator	Hakes Brothers				
Contact name & title	Chris Hakes				Mark Asplund
e-mail	chris@hakesbrothers.com				mark.asplund@hakesbrothers.com
Contact Phone #	505-842-1700				505-873-8780
COA Inspector	Thomas Evans		Start/End Time:	1:00 PM/1:30 PM	
Construction Phase:	Vertical				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up
Weather at time of inspection?	clear		Temperature:	~ 62	
Estimated date of last storm 0.25" or greater	2/22/2021				
Item Number	Deficiency/ Corrective Action				
1	Install and maintain inlet protection				
2	Use proper containers for construction and domestic waste				
3					
4					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:		

Notes:	Provide latest self-inspection report.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 04/22/2021