

## City of Albuquerque Stormwater Construction Site Inspection Report

Operator	CO9E NMR10		oject Name:					
4/6 Operator			oject Nume.	ne: Catalonia at The Trails				
Operator	12022	JO2ET LO	cation:	V	Voodmont Ave. and Paseo Del Norte			
	4/6/2022 Owner		Contractor					
	Operator		PV Trails Albuquerque, LLC					
Contact name & title		Kevin Wechter						
e-mail		kwechter@pacventures.com						
Contact Phone #		858-625-0100						
COA Inspector		Doug Hughes			Start/End Tim	ne: 3:30pm		
Construction Phase:			Home		n & Final Stabi			
Type of Inspection:			Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	clea	r		erature: ~	71	
Estimated date of last storm 0.25" or greater 3/23/2022								
Item								
	Deficiency/ Corrective Action							
Number								
1	The SWPPP was not available onsite. The Green Globe inspector said he was waiting to hear from Peter							
	Stein, and peter Stein said the inspector had it in his vehicle. The up-to-date SWPPP must be available							
	onsite. The Maps need to reflect current conditions including inactive areas, staging areas, and property							
	transferred to another operator, onsite and offsite ponds and other offsite areas. See G&D dated 2-13-							
2	All disturbed areas must satisfy the final stabilization criteria CGP2.2.12.b. or be transferred to another							
	operator. The City must verify stabilization prior to terminating inspections and permit coverage City							
	Code § 14-5-2-11(C)(2).							
3	There are several offsite areas of land disturbing activities associated with this project that need to be							
	shown on the SWPPP Map and that must be stabilized prior to terminating inspections and permit							
	coverage: 1) the pond west of the subdivision, 2) the northeast half of Woodmont along the frontage of							
	Catalonia, 3) The Pond and other disturbed area north of Catalonia, 4) The portion of Woodmont north							
	of Catalonia, 5) Pond "A5" at the east of Woodmont, and 6) the contractor's staging areas northeast of							
4	Woodmont The south engite need must also be stabilized							
4	The south onsite pond must also be stabilized.							
5	Silt fence needs to be added around all remaining areas of disturbance and should be shown on the							
	SWPPP Map.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	Requested	Latest re	port Date:			

Notes: All but the south row of lots have been transferred to DR Horton who has permit coverage. Offsite areas of land disturbance north of this site may eventually be included in the ESC Plan and Permit Coverage for the Preserve at Woodmont but they should be included in the scope of this project until they are transferred to the operator of that new project.

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505-924-3420) jhughes@cabq.gov

4/8/2022

James D. Hughes