

City of Albuquerque Stormwater Construction Site Inspection Report

SC File No.	C12E003B8		Project Name:		Fountain Hills Assisted Living		
IPDES Id. No. NMR10					4551 Vista Fuente Rd. NW		
11/2/2021		Owner			Contractor		
Operator		JB2C, LLC.			Chausa Dianas		
Contact name & title		Biju Cherian			Shawn Biazar		
e-mail		bijucherian@hotmail.com 505-264-8120			aecllc@aol.com 505-804-5013		
Contact Phone #							
COA Inspector Construction Phase:		Doug Hughes			Start/End Time: 8:30 AM sially mulched but not Stabilized.		
Type of In		Storm Event Past Storm			Event >0.25" 311/Complaint Follow Up		
	er at time of i				Tempe		39
	date of last s			ı	10/1/2021	iature.	33
	date of last's	101111 0.25	or greater				
Item	Deficiency/ Corrective Action						
Number							
1	The building is occcupied, onsite landscaping complete, but the stabilization of the offsite stockpile area						
	doesn't satisfy the criteria in CGP2.2.14.b. The stockpile is gone now. The sloped portion of the offsite						
	area has been mulched, but the mulch won't last 3 years, so it only provides temporary cover per						
	CGP2.2.14.a. The flat area on top of the slope is still bare dirt and is unprotected.						
	Permit coverage remains in effect until the ofsite area meets the Final Stabiilization criteria (2.2.14.b) so						
	the coverage must be posted for safe public viewing, self-inspectrion reports must continue and the up-						
	to-date SWPPP must be available onsite.						
	to-date Swiff indst be available offsite.						
2.4	D: 1 (f :: 2	()/()()	1				
=:=	Discharge off site?	(Y/N)	no			- 1 1-	
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	9/11/2	020
Notes: Superintendent not on site during this inspection, site not posted, SWPPP not available.							
The offsite disturbed area is inactive.							
							,

General Information

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: James D Hughes 505-924-3420

Jhughes@cabq.gov

James D. Hughes