

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	C12E0	,			Fountain Hills Assisted Living		
NPDES Id. No. NMR10		DO2DD Location:		4551 Vista Fuente Rd. NW			
11/2/2021		Owner			Contractor		
Operator		JB2C, LLC.			Chave Dianas		
Contact name & title		Biju Cherian			Shawn Biazar		
e-mail Contact Phone #		bijucherian@hotmail.com 505-264-8120			aecllc@aol.com 505-804-5013		
		Doug Hughes			Start/End Time: 8:30 AM		
COA Inspector							
Construction Phase:		Building occupied, offsite partially r Storm Event Past Storm Event					
Type of Inspection: Weather at time of i							
					Temperature: ~ 39 10/1/2021		
Estimated date of last storm 0.25" or greater 10/1/2021							
Item	Deficiency/ Corrective Action						
Number	Denoicitely/ corrective /iction						
1	The building is occcupied, onsite landscaping complete, but the stabilization of the offsite stockpile area						
	doesn't satisfy the criteria in CGP2.2.14.b. The stockpile is gone now. The sloped portion of the offsite						
	area has been mulched, but the mulch won't last 3 years, so it only provides temporary cover per						
	CGP2.2.14.a. The flat area on top of the slope is still bare dirt and is unprotected.						
	·						
	Permit coverage remains in effect until the ofsite area meets the Final Stabiilization criteria (2.2.14.b) so						
	the coverage must be posted for safe public viewing, self-inspectrion reports must continue and the up-						
	to-date SWPPP must be available onsite.						
2.1	Discharge off site?	(Y/N)	no				
	_			Latest rea	nort Date:	9/11/20	020
4	Sell Hispec	tion Reports	Requested	Latest re	port Date:	9/11/20	J2U
Notes: Superintendent not on site during this inspection, site not posted, SWPPP not available.							
The offsite disturbed area is inactive.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: James D Hughes 505-924-3420

Jhughes@cabq.gov