

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	C12E0	1 2		The Learning Experience			
NPDES Id. No.	NMR10		ocation:		4580 Nur	nzio Ave NW	
	5/2020	Property Own			Contractor		
Operator		Learning Lab Development PER LLC					
Contact name & title		Scooter Haynes					
Cantact Dhana #		scooter@scmpartners.com					
Contact Phone #		505 898-6622					
COA Inspector		Doug Hughes			Start/End Time:	10:50/11	:30AM
Construction Phase:				Eartl	nwork		
Type of Inspection:		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~							76
Estimated date of last storm 0.25" or greater							
Item							
	Deficiency/ Corrective Action						
Number							
1	The ESC Plan is still not approved and won't be until the G&D Plan is. The G&D Plan was re-submited						
	to Hydrology 9/18/2020 and is still in review.						
2	The Construction Entrance is still missing. Recent access has been through the adjacent Construction						
	Site, Smiles For Kids, and that trackout pad was removed and replaced with dirt. Both Construction						
	entrances must be reestablished and maintained.						
2.4		(1.45.1)					
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	ion Reports		Latest rep	oort Date:	9/23/20	020
					•		
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

9/29/20

James D. Hughes