

City of Albuquerque Stormwater Construction Site Inspection Report

| General Information | | | | | | | |
|---|---|-------------------------|-----------------|-------------------------|---------------------|-------------|-----------|
| ESC File No. | C12E0 | | | The Learning Experience | | | |
| NPDES Id. No. | NMR10 | Property Ow | Location: | | | nzio Ave NW | |
| 11/. Operator | 2/2020 | | Development PEI | R LLC | Contractor | | |
| Contact name & title | | Scooter Haynes | | | | | |
| | | scooter@scmpartners.com | | | | | |
| Contact Phone # | | 505 898-6622 | | | | | |
| COA Inspector | | Doug Hughes | | | Start/End Time: 2pm | | |
| Construction Phase: | | Earth | | | hwork | | |
| Type of Inspection: | | | | | | | Follow Up |
| Weather at time of inspection? Clear Temperature: ~ 76 | | | | | | | |
| Estimated date of last storm 0.25" or greater 9/26/2020 | | | | | | | |
| Item Number | Deficiency/ Corrective Action | | | | | | |
| | Cravel drive replaced at smiles 4 kids. No new violations | | | | | | |
| 1 | Gravel drive replaced at smiles 4 kids, No new violations | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | l | | | | | | |
| | l | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | <u> </u> | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | l | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 2.4 | | 5.63 | T N. | T | | | |
| 2.1 | Discharge off site? | (Y/N) | No | <u> </u> | | | |
| 4 | Self Inspect | tion Reports | | Latest rep | oort Date: | 10/28/2 | 020 |
| _ | _ | | | _ | | | |
| | | | | | | | |
| | | | | | | | |
| Notes: | | | | | | | |
| | | | <u> </u> | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

11/2/20

James D. Hughes