

City of Albuquerque Stormwater Construction Site Inspection Report

AND	MER							
			General I	nformation				
Project Name:		Paseo Nuevo						
Location:		6321 Holly		ESC File No.				
Site Contact Name &		Jeremy Zak - Skarsgard		Phone: (o)		505-362-1840		
Agency				Phone: (m)				
Owner		Skip Skarsgard - Paseo Nuevo		Phone: (o)	505-262-232	05-262-2323		
Owner's e-mail				Phone: (m)				
Inspection Date: CoA Stormwater Inspecto								
		earthwork						
Construction Phase: Type of Inspection: x		Regular Storm Event Post S			m Event >0.25" 311/Complaint Follow Up			
Type of It		Regular	Storm Event	1051 5101111	Event > 0.25	511/complaint	I ONOW OP	
Weath	er at time of i	nspection?	Cle	ar	Tempe	erature: ~	73*	
	date of last s					7/25/2020		
Item								
			Deficien	cy/ Correctiv	e Action			
Number								
1	Submit and acquire SWQ approval. (Install BMP's as outlined in approved plan)							
2	Sediment in access roadway to site requires mitigation.							
3	Cementous washout requires mitigation. Please provide washout location							
4	Please provide sediment BMP on the NW area of the site.							
5	Sediment build up exceeds the allowable 50% of silt fence height. Please mitigate.							
6	Inlet protection required on inlet in Holly approx. 150-180 If west of site location.							
7	Please provide the all SWPPP self-inspection reports. The initial report and all subsequent reports						t reports	
	thereafter to include rain events.							
	***CGI contractor conducting earthwork activities during construction. Site appears to h					ave		
	started during	; the month of July.						
2.1	Discharge off site?	(Y/N)	Yes		o Sediment S			
4	Self Inspect	ion Reports	s requested	Latest re	oort Date:	Not on	File	

Notes:	inspection conducted practicing social distancing.			

City of Albuquerque Stormwater Inspector Signature and date:Contact information:Timothy E. Sims - (505) 803-6155tsims@cabq.gov08/04/20