

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:		Legacy NAA Apartments II							
Location:		Alameda and San Pedro							
Site Contact Name &		Jeff Garcia		ESC File No.		C18E083			
Agency		Legacy - Superintendent		NPDES Id. No.		NMR1000QH			
Inspection	Inspection Date:		03/19/19 Start/End Time: 10						
CoA Stormwater Inspect		tor:	or: Timothy Sims, Stormwater Inspector						
Present Phase of		earthwork - clear and grub							
Construction:									
Type of Ir	nspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	x Follow Up		
					1				
Weath	er at time of i	nspection?			Tempe	rature: ~	55*		
		Clear							
I			ce site was Per	mitted?					
Clarify am	ount: (i.e <1	/4" to >3/4"):							
				ection					
			Maintenance						
CCP	CGP BMP / Activity Section		or Corrective		Locatio	Location and Notes			
			Action						
			Required						
1.5	Post a Notice Provide and maintain Natural buffer when								
2.2.1	Waters of the US <50ft.								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter		1					
2.2.3	Sediment control alo	ong any perimeter		1					
2.2.3	Sediment control alo	ong any perimeter							
2.2.3	Sediment control alo	ong any perimeter		1					
2.2.3	Sediment control alo								
2.2.4	Minimize sediment track out								

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	03.12.19

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	no issues observed
*Monitor	straw waddles, typical BMP on perimeter is a mulch sock. Mulch sock may be required
if straw fa	ils to perform as expected.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

on: Timothy Sims, 505-803-6155 or tsims@cabq.gov 03/19/19