

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C18E				Allaso Olivine			
NPDES Id. No.	NMR10059	9X & '5CC Location:			6925 Alameda Blvd NE			
1/17/2023		Owner		Contractor				
Operator		Titan Olivine, LLC			HB			
Contact name & title		Josh Rogers			Zach Gruen VP & Matthew Barnard SI			
e-mail		jrogers@titan-development.com 505-998-0111			zachg@Hbconstruction.com & leer@' 856-0404 & 250-2069			
Contact Phone #								
COA Inspector		Doug Hughes			Start/End Time: 10:00 AM			
Construction Phase:		framing/vertical Storm Event   Past Storm Event >0.25"   311/Complaint   Follow U					Ir.u	
Type of Inspection:					311/Complaint	Follow Up		
Weather at time of i			clea	r	Tempe 12/22/2023	rature: ~	40	
Estimated	date of last s	torm 0.25" or	greater		12/22/2023			
Item	Deficiency/ Corrective Action							
Number	Deficiency/ Corrective Action							
1	Sediment Trackout - sediment trails on Oakland and Louisiana between the lanes and the curb on both							
-	streets in Violation of CGP 2.2.4. <b>Required Mitigation</b> . Minimize sediment trackout per CGP 2.2.4.							
	Implement additional track-out controls as necessary to ensure that sediment removal occurs prior to							
	vehicle exit per CGP 2.2.4.c. Where sediment has been tracked-out from your site onto paved roads,							
	sidewalks, or other paved areas outside of your site, remove the deposited sediment by the end of the							
	same business day in which the track-out occurs or by the end of the next business day if track-out occurs							
	on a non-business day. Remove the track-out by sweeping, shoveling, or vacuuming these surfaces, or by							
	using other similarly effective means of sediment removal. You are prohibited from hosing or sweeping							
	tracked-out ne			·				
2	<b>SWPPP</b> - The operators' signatures were missing from the inspection reports in violation of CGP Appendix							
	G.11.2. <b>Required Mitigation:</b> The SWPPP, including the SWPPP Map, Self Inspection Reports, and							
	Corrective Action Reports, must be kept up-to-date per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3							
	and 7.3. Your SWPPP, corrective action log, site inspection, and any other compliance documentation							
	required under this permit, must be signed by the same responsable corporate officer that signs the							
	certification statement on your NOI or by a duly authorized representative of that person per CGP							
	Appendix G.11.2.							
3	Washout was on bare dirt in several locations arround the site and there weren't any lined washout							
	facuilities onsite. <b>Required Mitigation.</b> Remove and dispose contaminated soils and hardened concrete							
	with other waste in per CGP 2.2.3. Direct all future wash water from concrete, paint, and stucco into a leak-							
	proof container per CGP 2.3.4							
	proof container per cor 2.3.4							
2.4	D: 1	() (1)						
2.1	Discharge off site?	(Y/N)	yes	_				
4	Self Inspect	tion Reports		Latest re	port Date:	1/8/2	024	

Notes:	
The SWPP	P was located in the construction Trailer.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov