

General Permit SWPPP Inspection Allaso Olivine Site Name: Inspector: Marcos Valadez <u> Alameda @ Louisiana, Albuquerque, NM 87113</u> NMR10059X Bi-weekly -Permit #: **Inspection Frequency:** Last Precipitation 48h Forecast Last Rain Event Date of Visit: Apr 17, 2023, 8:16:14 AM Sunday, March 26, 2023, 0.02" 5% Chance of Rain **Inspection Form Instructions** Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action. **General Information** <u>Inspector's Qualifications</u> Trained and work experience - see inspector qualification page in section 2 of the SWPPP. Type of Inspection: During storm event Regular Post-storm event Weather Information **Last Storm Event Information** For information on the last storm event, see the weather event information at the end of this inspection. Weather at time of this inspection? Clear Cloudy Sleet Rain Snowing High Winds Partly Cloudy Have any discharges occurred since the last inspection? Yes If yes, what did the water look like at the time of the discharge? Are there any discharges at the time of this inspection? Yes If yes, what did the water look like at the time of the discharge? Is a rain gauge installed on site? Yes If yes, where is it located? Representative weather site is used to measure precipitation. Has the Rain Event Page been filled out? No Are there SDS sheets on site? Yes If yes, where are they located? If construction ceases on the site for more than 14 days, the site must be stabilized until construction resumes. **Date Construction Stopped Date Construction Resumed** Measures Taken to Stabilize the Site: Construction Phasing Verify what stage of construction the project is in, and record dates when activities started and were completed. Installed BMPs Completed Started: Completed: 3/2023 Site Clearing and Grading Started Started: 3/2023

Completed:

Started:

Completed:

Installing Utilities



General Permit SWPPP Inspection Allaso Olivine Site Name: Inspector: Marcos Valadez <u> Alameda @ Louisiana, Albuquerque, NM 87113</u> NMR10059X Bi-weekly -Permit #: **Inspection Frequency:** Last Rain Event Last Precipitation 48h Forecast **Date of Visit:** Apr 17, 2023, 8:16:14 AM Sunday, March 26, 2023, 0.02" 5% Chance of Rain **Building Structure** Started: Completed: Paving and Walks Started: Completed: Final Grading/Stabilize Site Started: Completed: Other Started: Site-specific BMPs The corrective actions initiated and date completed are in the Corrective Action Log List of BMPs Installed: Silt fence, stabilized construction entrance, portable toilet Are all of the above controls installed? No Do any of the above controls need maintenance? Yes If any of the controls have not been installed or require maintenance, please list the control and explain. Are the BMPs shown on the map? No Were there any changes to the SWPPP? Yes Has the SWPPP been updated? Yes Were the changes to the SWPPP implemented within 7 days? Yes

Oversight Issues

Maintenance Required?

Implemented?

Notes:

List any new BMPs needed:

A list of corrective actions will be supplied with this inspection.

1. Are all slopes and disturbed areas not actively being worked properly stabilized?

Maintenance Required? No Yes

2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?

Implemented?

No N/A

N/A

No

No new BMP's needed at this time.

inspection.

Yes

Yes

Dirt work in progress. The site looked good at the time of

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

Implemented?

No N/A



Implemented?

| | | | | _ | |
|---|--|---|---|-----------------------------------|--|
| | | mit SWPPP Inspection | | | |
| Site Name: | <u>Allaso Olivine</u> <u>Alameda @ Louisiana, Albuquerque, NM 87113</u> | Inspector: | Marcos Valadez | | |
| Permit #: | NMR10059X | Inspection Frequency: | Bi-weekly - | | |
| Date of Visit: | Apr 17, 2023, 8:16:14 AM | Last Rain Event | Last Precipitation Sunday, March 26, 2023, 0.02" | 48h Forecast 5% Chance of Rain | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 4. Are discharge poin | nts and receiving waters free of any sediment deposits? | | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 5. Are storm drain in | lets properly protected? | | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 6. Is the construction | n exit preventing sediment from being tracked into the stree | et? | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 7. ls trash/litter from | n work areas collected and placed in dumpsters? | | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 8. Are washout facili | <u>ties (e.g., paint, stucco, concrete) available, clearly marked,</u> | and maintained? | | | |
| Implemented? | | | | | |
| | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 9. Are vehicle and eq | <u>uipment fueling, cleaning, and maintenance areas free of s</u> | <u>pills, leaks, or any other deleterious</u> | material? | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired | Yes | No N/A | | |
| 10. Are materials tha | at are potential storm water contaminants stored inside or u | under cover? | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 11. Are non-storm water discharges (e.g., wash water, dewatering) properly controlled? | | | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 12. Has the Site map | been updated to reflect current conditions? | | | | |
| Implemented? | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 13. Is the NOI posted? | | | | | |
| Implemented? | | | | | |
| , | | Yes | No N/A | | |
| Maintenance Requ | ired? | Yes | No N/A | | |
| 14. Were previous corrections made within 7 days of last inspection or before the next storm event? | | | | | |

Yes



General Permit SWPPP Inspection Allaso Olivine Site Name: Inspector: Marcos Valadez <u> Alameda @ Louisiana, Albuquerque, NM 87113</u> Permit #: NMR10059X Bi-weekly -**Inspection Frequency:** Last Precipitation Last Rain Event 48h Forecast Date of Visit: Apr 17, 2023, 8:16:14 AM Sunday, March 26, 2023, 0.02" 5% Chance of Rain

Maintenance Required?

Yes No N/A

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

Are there any signs of hazardous materials being exposed to storm water runoff?

Yes No

Have there been any reportable quantities releases of hazardous materials?

Yes No

Additional Notes

Certification & Signatures

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X Marcos Valadez Date April 17, 2023 at 8:44:30 AM MDT

Title Inspector




| General Permit SWPPP Inspection | | | | |
|---------------------------------|--|-----------------------|--|-----------------------------------|
| Site Name: | <u>Allaso Olivine</u> <u>Alameda @ Louisiana, Albuquerque, NM 87113</u> | Inspector: | Marcos Valadez | |
| Permit #: | NMR10059X | Inspection Frequency: | Bi-weekly - | |
| Date of Visit: | Apr 17, 2023, 8:16:14 AM | Last Rain Event | Last Precipitation Sunday, March 26, 2023, 0.02" | 48h Forecast 5% Chance of Rain |

Photos










| General Permit SWPPP Inspection | | | | |
|---------------------------------|--|-----------------------|--------------------|--------------|
| Site Name: | <u>Allaso Olivine</u> <u>Alameda @ Louisiana, Albuquerque, NM 87113</u> | Inspector: | Marcos Valadez | |
| Permit #: | NMR10059X | Inspection Frequency: | Bi-weekly - | |
| Date of Visit: | Apr 17, 2023, 8:16:14 AM | Last Rain Event | Last Precipitation | 48h Forecast |

Weather History



All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



| General Permit SWPPP Inspection | | | | |
|---------------------------------|--|-----------------------|--------------------|--------------|
| Site Name: | <u>Allaso Olivine</u> <u>Alameda @ Louisiana, Albuquerque, NM 87113</u> | Inspector: | Marcos Valadez | |
| Permit #: | NMR10059X | Inspection Frequency: | Bi-weekly - | |
| Date of Visit: | Apr 17, 2023, 8:16:14 AM | Last Rain Event | Last Precipitation | 48h Forecast |

There Are No Action Items