

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information											
Project Nar	me:	Alameda Crossing (Campo del Norte)									
Location:		alameda and louisiana									
Site Contact Name &		Troy Crutchfield - Pulte		ESC File No.	C18E102						
Agency			ield2@pulte.co		NMR100LO						
Inspection Date:			Start/End Time: 12	210/1300hrs							
	water Inspecto										
Construction Phase: Type of Inspection: x		home construction   Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up									
Type of It	nspection: x	Regular	Storm Event	Post Storm	event >0.25	311/Complaint	Follow Up				
Weath	er at time of i	nspection?	Clea	ar	Tempe	rature: ~	41*				
Estimated	date of last s	storm 0.25" o	or greater			11/27/2020					
Item	tom										
Number	Deficiency/ Corrective Action										
Humber											
1	Please provide latest SWPPP self-inspection report.										
2	Concrte Washouts. Mitigate all illicit concrete washouts on site. Utilize provided concrete										
	washout facility.										
3	Inlet protection requires refreshing.										
4	Waste not in acceptable containers. Place all waste in an acceptable container.										
5	Sediment in street. Remove and prevent sediment from entering the street.										
6	Paint washout and overspray requires mitigation. Ensure trades utilize appropriate BMP to prev										
	an issue.										
2.1	Discharge off site?	(Y/N)	No								
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	9/2/20	19				

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155