

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Na	me:	Alameda Crossing (f.k.a. Campo del Norte)						
Location:				ESC File No.	NI	NPDES Id. No.		
Site Contact Name &		Chris Montoya - Pulte		Phone: (o)				
Agency		Christopher.Montoya@PulteGroup.com		Phone: (m)	50	05-227-7727		
Owner		Pulte Homes		Phone: (o)				
Owner's e-mail				Phone: (m)				
Inspection Date:			art/End Time:	7am				
CoA Stormwater Inspector: Doug Hughes								
Construction Phase: home construction								
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up								
			01	ı	<del>-</del> -		20	
Weath	er at time of i	inspection?	Cle	ar	Temperatu	ure: ~	30	
Estimated date of last storm 0.25" or greater 10/27/2020								
Item	Item Deficiency (Constant to Author							
Number	Deficiency/ Corrective Action							
	NDDES		<u> </u>					
1	NPDES not Posted for public viewing							
2	Self-Inspection reports not provided							
3	SWPPP Stormwater team not provided							
	3WTT Stormwater team not provided							
2.1	Discharge off site?	(Y/N)	No					
				1		C 14.4 10.00	10	
4	Self Inspec	tion Reports	requested	Latest rep	ort Date:	6/11/202	ĽU	
Notes: Inspection conducted adhering to Covid-19 constraints								
, , , , , , , , , , , , , , , , , , , ,								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes - 924-3420

jhughes@cabq.gov 11/10/20 James D. Hughes