

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:		Campo del Norte							
Location:		Signal & Alameda							
Site Contact Name &		Kevin Patton		ESC File No.		C18E102			
Agency		Pulte Homess		NPDES Id. No.		NMR1001L0			
Inspection Date:		02/12/19 Start/End Time:		100-1130hrs					
CoA Stormwater Inspec		tor:	Timothy Sims, Stormwater Inspector						
Present Phase of		civil, cutting road grade, constructing walls							
Construction:									
Typer of Inspection:									
	х	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up		
Weath	er at time of i	•			Tempature: ~ 31*		31*		
		Clear							
Has there been a storm event since site was Permitted?									
Clarify amount: (ie. <1/4" to >3/4"):									
				pection					
			Maintenance or Corrective						
CGP	BMP /	BMP / Activity		2	Location and Notes				
Section			Action Required						
1.5	Post a	Notice	Required						
1.5	Provide and maintain Na								
2.2.1	Waters of the US <50ft.	of the US <50ft.							
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	.2.3 Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	.2.3 Sediment control along any perimeter								
2.2.3									
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter X		silt fence repair north end of Sugarrite Trail						
2.2.4	Minimize sediment track out					2			

2.2.5	Manage stock piles				
2.2.6	minimize dust				
2.2.10	Protect storm drain inlets				
2.2.10	Protect storm drain inlets				
2.2.11	Minimize erosion of conveyance channels				
2.2.12	Sediment Basins				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.3.1	Equiptment and vehicle fueling				
2.3.2	Equiptment and vehicle washing				
2.3.3	Building material storage	х	store mortar mix in approved containers		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage				
2.3.3	Construction and domestic wastes	х	domestic trash on south east side of site provide dumpster		
2.3.3	Construction and domestic wastes				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.	Х	mortar washout not using approved methods		
2.4	Dewatering				
2.1	Discharge off site? (Y/N)	No			
4	Self Inspection Reports	yes	Latest report Date:	requested	

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

all previous issues completed

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy Sims, 505-803-6155 or tsims@cabq.gov