

## City of Albuquerque Stormwater Construction Site Inspection Report

			General I	Information			
Project Name:		Rpohan Subdivision					
Location:		Eagle Rock & Wyoming					
Site Contact Name &		Rich Ganter- ti		ESC File No.		C19E042A_T	
Agency		richganter@l		NPDES Id. No.		NMR1001V3	
Inspection Date:				.155/1220hrs			
	water Inspector ction Phase:	r: IIIr	mothy E. Sims	Haman an			
	spection: x	Home construction  Regular   Storm Event   Post Storm Event > 0.25"   311/Complaint   x   Follow U					
туре от п	ispection. X	Regulai	Storin Event	Trost Storing	vent >0.23	[311/Complain	ı x fronow op
Weathe	er at time of i	nspection?	Cle	ar	Tempe	erature: ~	46*
Estimated	date of last s	torm 0.25" or				11/27/2019	
Item							
	Deficiency/ Corrective Action						
Number							
1	Too much sediment in street. Sweep and remove sediment from Street						
2	Provide NPDES posting. Posting must be visible from R.O.W.						
3	Silt fence requires repair or reinstallation.						
4	A sediment BMP is required for lots not stabilized. (completed houses)						
5	Washouts on the northern most lot requires mitigation.						
6	please provide latest SWPPP self-inspection report.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	requested	Latest rep	ort Date:	10/18	/2019
				•			
Matan							
Notes:							

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

12/11/19\_\_\_\_\_