



City of Albuquerque Stormwater Construction Site Inspection Report

General Information					
ESC File No.	C19E042_T	Project Name:	Rohan Subdivision		
NPDES Id. No.	NMR1001V3	Location:	7519 Eagle Rock NE		
5/3/2021	Owner			Contractor	
Operator	Tiara Homes				
Contact name & title	Rich Gantner				
e-mail	richgantner@lobo.net				
Contact Phone #	505-797-6655				
COA Inspector	Thomas Evans		Start/End Time:	12:30 PM/12:35 PM	
Construction Phase:	Home construction				
Type of Inspection:	Regular	Storm Event	Past Storm Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection?	cloudy		Temperature: ~	66	
Estimated date of last storm 0.25" or greater	4/28/2021				
Item Number	Deficiency/ Corrective Action				
1	Sediment/leaves built up around inlet. Remove sediment/leaves around the inlet. Reposition the wattle to prevent sediment from entering the inlet.				
2	Washout in the driveway. Direct wash water from concrete, paint, and stucco into a leak-proof container per CGP 2.3.4. Remove and dispose of hardened concrete with other waste per CGP 2.3.3.				
3	Construction waste not in acceptable waste container. Place construction waste in an acceptable container with a lid/tarp. (CGP 2.3.3)				
4					
5					
2.1	Discharge off site? (Y/N)	no			
4	Self Inspection Reports	Requested	Latest report Date:	9/11/2020	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
 Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov *Thomas Evans* 05/04/2021