

City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	nformation				
ESC File No.	C19E042_T		roject Name:	Rohan Subdivisior		Subdivision		
NPDES Id. No.	NMR1001V3		ocation:		7519 Eagle Rock NE			
6/30/2021		Owner		Contractor				
Operator		Tiara Homes						
Contact name & title		Rich Gantner						
e-mail		<u>richgantner@lobo.net</u>						
Contact Phone #		505-797-6655						
COA Inspector		Thomas Evans			Start/End Time: 12:35 PM-12:45 PM			
	ction Phase:				onstruction			
Type of Inspection: Regular Storm Event Past Storm Event >0.25" 311/Complaint Fol						Follow Up		
Weath	er at time of i	inspection?	rair	۱	Tempera	ature: ~	70	
Estimated	date of last s	storm 0.25" o	r greater		6/28/2021			
Item								
Number	Deficiency/ Corrective Action							
1	Sediment/leaves built up around inlet. Remove sediment/leaves around the inlet. Reposition the							
	wattle to prevent sediment from entering the inlet.							
2	SWPPP not available on site and the location of it is not on the NOI posting. Identify location of SWPPP							
	on the NOI posting.							
3	No sediment control BMP along perimeter fence of home lot. Install a sediment control BMP along the							
_	fenceline to prevent sediment from exiting the site.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	Requested	Latest re	port Date:	9/11/2	020	

Notes:	No activity on site. Photos were taken on June 1, 2021 after a rain event on May 31.				
With the exception of the inlet protection, site conditions appear to the be the same.					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215) tevans@cabq.gov

Thomas Evans of

06/30/2021