

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Holly Senior	Living / Amaran S	enior Living			
Location:		9100 Holly	<u> </u>				
Site Contact Name & Agency		Xenia - Paaru	ı	ESC File No.		C20E079	
		si@paarugr		NPDES Id. No.		NMR10025V	
Inspection Date:				840/0905hrs			
	vater Inspector		Timothy E. Sims	· ·			
Construction Phase: foundation							
Type of In	spection: x	Regular	Storm Event		ent >0.25"	311/Complaint	Follow Up
Weath	er at time of i	nspection?	Cle	ar	Tempe	rature: ~	23*
Estimated	date of last s	torm 0.25" (12/2/2019	
Item	Deficiency/ Corrective Action						
Number	,,						
1	Sediment build up in Holly requires mitigation. All track out must be cleaned/removed by end						
	of business day. A follow up inspection will occur tomorrow. Mitigate sediment in Holly.						
2	Domestic waste not in acceptable container on the east side of the site. Train trades to						
	utilize provided waste containers.						
3	The silt fence on the north side requies proper installation or provide equal BMP.						
			•	1			
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	ion Reports		Latest rep	oort Date:	12/9/20)19
Notes:							

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155

11110th 1 11110th 1 2: 3hh 3 (303) 003 013.

<u>tsims@cabq.gov</u> 12/16/19