



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

|                            |   |                                      |  |  |                                    |
|----------------------------|---|--------------------------------------|--|--|------------------------------------|
| Project Name:              | Swim Lab  |                                      |  |  |                                    |
| Location:                  | 8120 Ventura  |                                      |  |  |                                    |
| Site Contact Name & Agency | Jason - Klinger<br><a href="mailto:jasont@klingerllc.com">jasont@klingerllc.com</a> | ESC File No.                         | C20E082  |  |                                    |
|                            |   | NPDES Id. No.                        | NMR10028F  |  |                                    |
| Inspection Date:           | 08/26/19  | Start/End Time:                      | 0930/0945hrs                                     |  |                                    |
| CoA Stormwater Inspector:  | Timothy E. Sims   |                                      |  |  |                                    |
| Construction Phase:        | earthwork   |                                      |  |  |                                    |
| Type of Inspection:        | <input checked="" type="checkbox"/> Regular   | <input type="checkbox"/> Storm Event | <input type="checkbox"/> Post Storm Event >0.25" | <input type="checkbox"/> 311/Complaint | <input type="checkbox"/> Follow Up |

|   |          |                |     |
|---|----------|----------------|-----|
| Weather at time of inspection?                | Clear    | Temperature: ~ | 82* |
| Estimated date of last storm 0.25" or greater | 7/7/2019 |                |     |

| Item Number | Deficiency/ Corrective Action  |    |                     |
|-------------|--|----|---------------------|
|             | no issues observed.  |    |                     |
|             | ***Please provide SWPPP inspection report with first SWPPP inspection. |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
|             |  |    |                     |
| 2.1         | Discharge off site? (Y/N)  | No |                     |
| 4           | Self Inspection Reports  |    | Latest report Date: |

|        |   |
|--------|---|
| Notes: | Entrance is swept daily/ as needed for track out. |
|        |   |
|        |   |
|        |   |
|        |   |
|        |   |

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 08/26/19