



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

|                            |                                                                                     |                                      |                                                  |                                        |                                    |
|----------------------------|-------------------------------------------------------------------------------------|--------------------------------------|--------------------------------------------------|----------------------------------------|------------------------------------|
| Project Name:              | Swim Lab                                                                            |                                      |                                                  |                                        |                                    |
| Location:                  | 8120 Ventura                                                                        |                                      |                                                  |                                        |                                    |
| Site Contact Name & Agency | Jason - Klinger<br><a href="mailto:jasont@klingerllc.com">jasont@klingerllc.com</a> | ESC File No.                         | C20E082                                          |                                        |                                    |
|                            |                                                                                     | NPDES Id. No.                        | NMR10028F                                        |                                        |                                    |
| Inspection Date:           | 11/18/19                                                                            | Start/End Time:                      | 0835/0900hrs                                     |                                        |                                    |
| CoA Stormwater Inspector:  | Timothy E. Sims                                                                     |                                      |                                                  |                                        |                                    |
| Construction Phase:        | earthwork                                                                           |                                      |                                                  |                                        |                                    |
| Type of Inspection:        | <input checked="" type="checkbox"/> Regular                                         | <input type="checkbox"/> Storm Event | <input type="checkbox"/> Post Storm Event >0.25" | <input type="checkbox"/> 311/Complaint | <input type="checkbox"/> Follow Up |

|                                               |           |                |     |
|-----------------------------------------------|-----------|----------------|-----|
| Weather at time of inspection?                | Clear     | Temperature: ~ | 53* |
| Estimated date of last storm 0.25" or greater | 11/7/2019 |                |     |

| Item Number | Deficiency/ Corrective Action |    |                                |
|-------------|-------------------------------|----|--------------------------------|
|             | no issues observed.           |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
|             |                               |    |                                |
| 2.1         | Discharge off site? (Y/N)     | No |                                |
| 4           | Self Inspection Reports       |    | Latest report Date: 11/15/2019 |

|        |                                                   |
|--------|---------------------------------------------------|
| Notes: | Entrance is swept daily/ as needed for track out. |
|        |                                                   |
|        |                                                   |
|        |                                                   |
|        |                                                   |
|        |                                                   |

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 11/18/19