

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:		Montecito Vistas							
Location:		Vista Viejos & Montecito							
Site Contact Name &		Kevin Patton		ESC File No.	D09E005				
Agency		kevin.patton@pultegroup.com		n NPDES Id. No.	NMR1000BZ				
Inspection Date:		04/03/19 Start/End Time:		015/1130hrs					
CoA Stormwater Inspec		ctor:	Timoth		ns, Stormwater Inspector				
Present Phase of		-	wall construction, home construction						
Construction:									
Type of Ir	spection:	Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow U							
Weather at time of i		-			Temperature: ~ 57*				
		Clear							
Has there been a storm event since site was Permitted?									
Clarify amount: (i.e <1/4" to >3/4"): yes, >1/4"									
Inspection									
			Maintenance						
CGP	BMP / Activity		or Corrective Action		Location and Notes				
Section			Required						
1.5	Post a Notice								
2.2.1	Provide and maintain Na Waters of the US <50ft.	atural buffer when							
2.2.1	Sediment control along any perimeter		x	<u>т</u>	Track out pad Retablo west end				
2.2.3	Sediment control along any perimeter								
2.2.3			x	curb cuts a	and curb BMP's- depress or provide BMP				
2.2.3	Sediment control along any perimeter Sediment control along any perimeter		x		Re-establish silt fence at outfall pipe				
2.2.3	Sediment control along any perimeter		^						
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control along any perimeter			1					
2.2.3	Sediment control along any perimeter								
2.2.3	Sediment control alo			1					
2.2.3	Sediment control along any perime			1					
2.2.3	Sediment control alo	• • •		1					
2.2.4	Minimize sediment t	•							

2.2.5	Manage stock piles				
2.2.6	minimize dust				
2.2.10	Protect storm drain inlets				
2.2.10	Protect storm drain inlets	х	out fall to the NE clean trash		
2.2.11	Minimize erosion of conveyance channels				
2.2.12	Sediment Basins				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.2.14	Stabilize exposed portions of the site				
2.3.1	Equipment and vehicle fueling				
2.3.2	Equipment and vehicle washing				
2.3.3	Construction and domestic wastes	х	Lot to the east of site - clean construction debris/ litter		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage				
2.3.3	Construction and domestic wastes	х	clean site of construction debris and litter		
2.3.3	Construction and domestic wastes				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.3.4	Washing applicators used for paint, stucco, concrete, etc.				
2.4	Dewatering				
2.1	Discharge off site? (Y/N)	No			
4	Self Inspection Reports		Latest report Date: 3/4/2019		

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes: Site requires vigorous maintenance. Several outstanding issues, mitigate issues.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

n: Timothy Sims, 505-803-6155 or tsims@cabq.gov 04/03/19