

## City of Albuquerque Stormwater Construction Site Inspection Report

| General Information  |   |   |                     |                                   |                               |                     |            |  |  |
|--|---|---|---------------------|-----------------------------------|-------------------------------|---------------------|------------|--|--|
| ESC File No.   | D10E002D  |   | Project Name:       |                                   | La Cuentiasta III & Stockpile |                     |            |  |  |
| NPDES Id. No.  | NMR10   | 004P9 L                                     | 4P9 Location:       |                                   | Rosa Parks and Kimmick        |                     |            |  |  |
| 0, 2, 2022   |   | Owner                                       |                     |                                   | Contractor                    |                     |            |  |  |
| Operator   |   | Pulte Homes of NM                           |                     | Guzman Construction               |                               |                     |            |  |  |
| Contact name & title   |   |   |                     | Rudy Guzman                       |                               |                     |            |  |  |
| e-mail   |   | Kevin.Patton@PulteGroup.com<br>505-341-8591 |                     | rudy@guzmancs.com<br>505-459-3128 |                               |                     |            |  |  |
| Contact Phone # COA Inspector  |   | Doug Hughes                                 |                     | Start/End Time: 7:45AM            |                               |                     |            |  |  |
| •  |   | 1 0   |                     | ,                                 |                               |                     |            |  |  |
| Construction Phase: Staging Type of Inspection: Regular Storm Event Past Storm Event >0.25" 311/Complaint Follow |   |   |                     |                                   |                               |                     | Follow Up  |  |  |
|  |   |   |                     |                                   |                               |                     | 81         |  |  |
| Weather at time of inspection? Clear Temperature: ~ 81 Estimated date of last storm 0.25" or greater 7/24/2022   |   |   |                     |                                   |                               |                     |            |  |  |
|  |   | 0.25 0                                      | r greater           |                                   | ,, = ., = ===                 |                     |            |  |  |
| Item   | Deficiency/ Corrective Action   |   |                     |                                   |                               |                     |            |  |  |
| Number   | 2 5.1.5(3.1.5)  |   |                     |                                   |                               |                     |            |  |  |
| 1  | BMPs were missing at the staging/stockpile area.  |   |                     |                                   |                               |                     |            |  |  |
| 2  | The property owner's NOIs are missing for the stockpile/staging area, so it doesn't have NPDES Permit   |   |                     |                                   |                               |                     |            |  |  |
|  | coverage. NPDES Permit coverage is required for all disturbed areas. Tracts 1-5 Block 6 are entirely  |   |                     |                                   |                               |                     |            |  |  |
|  | covered by recent land disturbing activities. There is also a large area of land disturbance on the portion   |   |                     |                                   |                               |                     |            |  |  |
|  | of Tract 1 Blk 2 Plat of Tr1 Blk 2 Volcano Cliffs Subdivision Unit 26 that is due east of Tract 5 and where a   |   |                     |                                   |                               |                     |            |  |  |
|  | water tank, porta potty, and other haul roads are located. An additional haul road is located on Tract 8  |   |                     |                                   |                               |                     |            |  |  |
|  | Blk 1.  |   |                     |                                   |                               |                     |            |  |  |
| 3  |   | n't available on                            | site for the area o | of Construction                   | on Support Acti               | vities. Pulte's SWI | PPP didn't |  |  |
|  | A SWPPP wasn't available onsite for the area of Construction Support Activities. Pulte's SWPPP didn't include the required information on the staging area (NOIs & SWPPP Map of BMPs) either. Pulte's |   |                     |                                   |                               |                     |            |  |  |
|  | SWPPP reports are not up-todate. The Doc Box won't shut tightly, and SWPPP is being damaged by  |   |                     |                                   |                               |                     |            |  |  |
|  | weather.  |   |                     |                                   |                               |                     | ~~~~,      |  |  |
| 4  | weather.  |   |                     |                                   |                               |                     |            |  |  |
|  |   |   |                     |                                   |                               |                     |            |  |  |
|  |   |   |                     |                                   |                               |                     |            |  |  |
| 2.1  | Discharge off site?   | (Y/N)                                       | no                  |                                   |                               |                     |            |  |  |
| 4  | Self Inspec   | tion Reports                                | Requested           | Latest re                         | port Date:                    | 7/7/20              | )22        |  |  |

| N  | otes: |
|----|-------|
| I۷ | DIES. |

The SWPPP is in the lockbox on Pulte's posting sign, and it is up-to-date, except the stockpile/staging area is missing. Eddie at Guzman said the new intent is to obtain permit coverage for only Tracts 4 and 5 in Block 6 and Tract 1 Block 2 and stabilize the rest with seed and agregate mulch.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov

8/2/2022

James D. Hughes