

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	D10E00	03_P P	roject Name:	Volcano Cliffs Subdivision				
NPDES Id. No.	NMR10	NMR1002X8 Location:			Alto Rey and Agua Fria			
7/12/2021		Owner		Contractor				
Operator		Pulte Homes			Pulte Homes			
Contact name & title					Brian Anderson			
e-mail		kevin.patton@pultegroup.com			brian.anderson@pultegroup.com			
Contact Phone #		505-341-8591			505-331-8711			
COA Inspector		Thomas Evans		Start/End Time				
Construction Phase:					/grading/vertical			
Type of Inspection:			Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up	
Weather at time of ir		nspection? clear		Temperature: ~ 73				
Estimated	date of last s	torm 0.25" or greater			7/6/2021			
Item	Deficiency / Constant in Aution							
Number	Deficiency/ Corrective Action							
	CM/DDD ask updated. Need to although property as DAD project property as a time to a start to a sta							
1	SWPPP not updated. Need to obtain signatures, BMP maintenance/corrective action logs, etc.							
2	Sediment in the streets/sidewalk. Remove sediment from streets/sidewalks daily.							
3	No inlet protection installed. Install inlet protection.							
4								
5								
6								
7								
			_					
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	Requested	Latest re	port Date:	7/1/20	21	

Notes:	Met with Angelica Saiz (superintendent) and discussed what needs to be updated in the
SWPPP. P	osting is there, but was knocked over. Angelica will put it back it up. Streets/sidewalks have
been swe	pt since last violation notice, but there is still some sediment remaining. One porta potty was
tipped ove	er. Angelica said they have had issues with people in the neighborhood tipping them over.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans 07/12/2021