

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	D17E0				Alvarado Roofing Headquarters			
NPDES Id. No. NMR10		006G4 Location:			9561 Central Ave NW			
11/19/2024		Owner			Contractor			
Operator		Kemper Commercial LLC			Alvarado Roofing Inc.			
Contact name & title		Craig Kemper			Craig Kemper			
e-mail		craig@alvaradoroofing.com			craig@alvaradoroofing.com			
Contact Phone #		505-842-7663			505-842-7663			
COA Inspector		Chancellor English			Start/End Time:	ime: 11am		
Construction Phase:					s, utilities			
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Weather at time of in		•			Temperature: ~ 65			
Estimated	date of last s	torm 0.25" c	orm 0.25" or greater			11/7/2024		
Item	Deficiency/ Corrective Action							
Number	Deficiency, corrective Action							
1	The inspection reports available on-site were not current in violation of CGP Part 4.7.3. Required							
	mitigation: You must keep a copy of all inspection reports at the site or at an easily accessible location,							
	so that it can be made immediately available at the time of an on-site inspection per CGP Part 4.7.3.							
			·					
2.4	n: 1	() (1)		<u> </u>				
	Discharge off site?	(Y/N)	no	lake t	and Date 1	0/40/20	224	
4	Seit inspect	ion Reports	Yes	Latest rep	oort Date:	9/19/20	J24	
Notes:								
The most current inspection report was requrested.								
There's the second officers.								
							l	

City of Albuquerque Stormwater Inspector Signature and date: 2/6/2025

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English