

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Name:			Overture Senio	or Active Adult					
Location:			6441 Palomas						
Site Contact Name &			Clay - Pavillion		ESC File No.		D18E056A		
Agency			cgriffin@pav	ilionconstruct	NPDES Id. No.		NMR1001Q2		
Inspection Date:			12/11/19 St	art/End Time: 0	830/0845hrs				
CoA Storm	water Inspec	tor	: Ti	mothy E. Sims					
Constru	ction Phase:		•	•	Plumbing, v	wall building			
Type of Inspection:			Regular	Storm Event	Post Storm I	vent >0.25"	311/Complaint	x Follow Up	
Weath	er at time o	of ir	spection?	Cle	ar	Tempe	rature: ~	31*	
Estimated date of last storm 0.25" or greater 11/27/2019									
Item									
	Deficiency/ Corrective Action								
Number									
	all previous issues mitigated, no new issues observed with this inspection								
2.1	Discharge off site	?	(Y/N)	No					
4			ion Reports	.,,	Latest reg	ort Date:	12/9/2	019	
-τ	och mop		ion reports	l .	Luccscie	ort Date.	12/ 3/ 2	.019	
Notes:									

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

12/11/19_____