

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	D19E			Palomas Peak Phase 2			
NPDES Id. No.	NMR10			8310 Palomas Ave. NE			
4/6/2021		Owner			Contractor		
Operator		Palomas Peak, LLC.					
Contact name & title		Eric Tidmore					
e-mail		eric@trinitynm.com					
Contact Phone #		505-830-1928					
COA Inspector		Thomas Evans			Start/End Time: 1:45 PM/2:30 PM		
	tion Phase:				ading		
Type of Inspection:		Follow Up	Storm Event		Event >0.25"	311/Complaint	
Weather at time of inspection? Clear Temperature: ~						ature: ~ 2/22/2021	70
Estimated date of last storm 0.25" or greater							
Item	Deficiency/ Corrective Action						
Number	Deficiency/ Corrective Action						
1	Silt fence needs to repaired or replaced						
•	Site 151150 115580 to Topanion of Topanion						
2	Congrete washaut peeds to be remained and disposed						
2	Concrete washout needs to be removed and disposed.						
3							
4							
5							
	,						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	ion Reports	Requested	Latest rei	port Date:		
	Jen mopee	пол перега	, itequestes				
Notes: Vehicles are parking on the west lot. No construction activity. Need latest inspection							
report. NPDES permit sign is posted in East lot.							
Topoliti iti beo perime sigir is posecu in euseroti							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Themo 6 4/8/2021